




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE2441</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9920234005																								
<b>Technician Name :</b>	Yasin Shaikh		<b>Technician Mobile :</b>	8689802313																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	16-12-2020 01:15:11																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Ashford Royale	Customer's Mobile :	9920234005	Name :	Deepak Sir																				
<b>Address :</b>																									
Mumbai , , , 400078 , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	BMS Room camera issue																								
<b>Technician Comment :</b>	all camera working OK 4 & 5 camera fluctuate issue by solved Karbonn and reconnection now working OK																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	all camera working OK 4 & 5 camera fluctuate issue by solved Karbonn and reconnection now working OK																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>16-12-2020 04:05:57</td><td>YasinShaikh</td><td>Completed</td><td>all camera working OK 4 &amp; 5 camera fluctuate issue by solved Karbonn and reconnection now working OK</td><td></td></tr><tr><td>16-12-2020 01:15:32</td><td>YasinShaikh</td><td>New</td><td></td><td>-</td></tr><tr><td>16-12-2020 01:15:12</td><td>YasinShaikh</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	16-12-2020 04:05:57	YasinShaikh	Completed	all camera working OK 4 & 5 camera fluctuate issue by solved Karbonn and reconnection now working OK		16-12-2020 01:15:32	YasinShaikh	New		-	16-12-2020 01:15:12	YasinShaikh	New		-
Date Time	Technician Name	Status	Remark	Sign																					
16-12-2020 04:05:57	YasinShaikh	Completed	all camera working OK 4 & 5 camera fluctuate issue by solved Karbonn and reconnection now working OK																						
16-12-2020 01:15:32	YasinShaikh	New		-																					
16-12-2020 01:15:12	YasinShaikh	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>31-07-2023 12:52:32</td><td>Ravi Rajbhar</td><td></td></tr><tr><td>31-03-2023 10:37:16</td><td>Ravi Rajbhar</td><td>b wing 202 video door phone out door camera reinstallation done and ok working done and 750 cash collat</td></tr></tbody></table>					Date Time	Technician Name	Remark	31-07-2023 12:52:32	Ravi Rajbhar		31-03-2023 10:37:16	Ravi Rajbhar	b wing 202 video door phone out door camera reinstallation done and ok working done and 750 cash collat											
Date Time	Technician Name	Remark																							
31-07-2023 12:52:32	Ravi Rajbhar																								
31-03-2023 10:37:16	Ravi Rajbhar	b wing 202 video door phone out door camera reinstallation done and ok working done and 750 cash collat																							