## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status Det	cails: VE2731						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9920234005						
Technician Name :	Siddhesh Chavan		Technician Mobile :		8080922985		
Ticket Type:	Complain	Date & Time :	24-02-202	1 09:57:38			
Vendor Details :							
Company Name/Client Name :	Ashford Royale	Customer's Mobile :	99202340	05	Name :	Deepak Sir	
Address:							
Mumbai , , , 4000'	78 , Maharashtra						
AMC Details:							
Expiry Date :	01-01-1970 05:30:	00	Type:				
<b>Product Name:</b>	CCTV		•				
Complain:	cannot view cameras on TV and some cameras issue						
Technician Comment :	dvr video output working and tv issue and 1) D wing = 801 vdp working ok 1302 vdp video issue resolved 2703 vdp reinstall and 750 charge colled and 2)c wing 1101 flat lock 3) 1301 vdp adepter issue pending 4) 5 camera video issue pending						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	dvr video output working and tv issue and 1) D wing = 801 vdp working ok 1302 vdp video issue resolved 2703 vdp reinstall and 750 charge colled and 2)c wing 1101 flat lock 3) 1301 vdp adepter issue pending 4) 5 camera video issue pending						
Status History :	Date Time	Technician Name	Status	Remark		Sign	
	24-02-2021 05:47:24	Siddhesh Chavan	Completed	dvr video output working and tv issue and 1) D wing = 801 vdp working ok 1302 vdp video issue resolved 2703 vdp reinstall and 750 charge colled and 2)c wing 1101 flat lock 3) 1301 vdp adepter issue pending 4) 5 camera video issue pending			
	24-02-2021 09:57:57	Siddhesh Chavan	New			-	
	24-02-2021 09:57:38	Siddhesh Chavan	New			-	
Previous	Date Time	Technician Name		Remark			
Complain History :	31-07-2023 12:52:32		ATU-AAATT-AA				
Ü	31-03-2023 10:37:16	10:37:16 Ravi Rajbhar b wing 202 video door phone out door camera reinstallat done and ok working done and 750 cash collat					