




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE3683</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9920234005																								
<b>Technician Name :</b>	Yogesh Desai		<b>Technician Mobile :</b>	8080922963																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	23-08-2021 04:46:47																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Ashford Royale	<b>Customer's Mobile :</b>	9920234005	<b>Name :</b>	Deepak Sir																				
<b>Address :</b>																									
Mumbai , , , 400078 , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																						
<b>Product Name :</b>	VDP																								
<b>Complain :</b>	d wing 1003 vdp reinstallation 750/- charges																								
<b>Technician Comment :</b>	Vdp reinstallation done in flat no 1003.new adapter also installed as the old one not working. cash received of 1300 ? from client.																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	Vdp reinstallation done in flat no 1003.new adapter also installed as the old one not working. cash received of 1300 ? from client.																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>23-08-2021 05:48:37</td><td>YogeshDesai</td><td>Completed</td><td>Vdp reinstallation done in flat no 1003.new adapter also installed as the old one not working. cash received of 1300 ? from client.</td><td></td></tr><tr><td>23-08-2021 04:47:07</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>23-08-2021 04:46:47</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	23-08-2021 05:48:37	YogeshDesai	Completed	Vdp reinstallation done in flat no 1003.new adapter also installed as the old one not working. cash received of 1300 ? from client.		23-08-2021 04:47:07	YogeshDesai	New		-	23-08-2021 04:46:47	YogeshDesai	New		-
Date Time	Technician Name	Status	Remark	Sign																					
23-08-2021 05:48:37	YogeshDesai	Completed	Vdp reinstallation done in flat no 1003.new adapter also installed as the old one not working. cash received of 1300 ? from client.																						
23-08-2021 04:47:07	YogeshDesai	New		-																					
23-08-2021 04:46:47	YogeshDesai	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>31-07-2023 12:52:32</td><td>Ravi Rajbhar</td><td></td></tr><tr><td>31-03-2023 10:37:16</td><td>Ravi Rajbhar</td><td>b wing 202 video door phone out door camera reinstallation done and ok working done and 750 cash collat</td></tr></tbody></table>					Date Time	Technician Name	Remark	31-07-2023 12:52:32	Ravi Rajbhar		31-03-2023 10:37:16	Ravi Rajbhar	b wing 202 video door phone out door camera reinstallation done and ok working done and 750 cash collat											
Date Time	Technician Name	Remark																							
31-07-2023 12:52:32	Ravi Rajbhar																								
31-03-2023 10:37:16	Ravi Rajbhar	b wing 202 video door phone out door camera reinstallation done and ok working done and 750 cash collat																							