Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

E: vallabhsecure@yahoo.co.in						
Service Status Deta	ails: VE5107					
Priority:	Low					
Created By:	Admin - Apurva Vajaria					
Complaint Mob. No. :	9820053896					
Technician Name	Siddhesh Chavan		Technician Mobile : 8080922985			
Ticket Type :	Complain	Date & Time :	29-03-2022 04:03:06			
Vendor Details :			•			
Company Name/Client Name :	Bhoomi Enclave "C" Wing	Customer's Mobile :	9820053896		Name:	Deepak Sir
Address:						
Mumbai , , , , Mah	arashtra					
AMC Details :			_			
Expiry Date :	01-01-1970 05:30:00		Type:			
Product Name:	Ppm					
Complain:	cctv					
Technician Comment :	one camera disconnected by dvr side and reconnect bnc and camera started and all camera working ok and ppm done all camera cleaning					
Complain Operator :	Desktop - Apurva Vajaria					
Remark:	one camera disconnected by dvr side and reconnect bnc and camera started and all camera working ok and ppm done all camera cleaning					
Status History :	Date Time	Technician Name	Status	Remark		Sign
	29-03-2022 06:52:56	Siddhesh Chavan	Completed	one camera disconnected by dvr side and reconnect bnc and camera started and all camera working ok and ppm done all camera cleaning		CV Jun
	29-03-2022 04:03:19	Siddhesh Chavan	New			-
	29-03-2022 04:03:06	Siddhesh Chavan	New			-
Previous Complain History :	Date Time	Technician Name	Remark			
	07-03-2022 10:10:58	3 Ravi Rajbhar	two camera issue resolved one camera lift second camera terrace recording going on in DVR			
	10-01-2022 11:02:30) YogeshDesai	lift camera not working due to cable issue cable faulty need to be changed. camera is ok one BNC & Dc connector used.			