

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2589																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9870067773																																		
Technician Name :	Mayur Yadav		Technician Mobile :	8411951301																															
Ticket Type :	New Installation	Date & Time :	18-01-2021 07:15:40																																
Vendor Details :																																			
Company Name/Client Name :	Scheitel Security Systems	Customer's Mobile :	9870067773	Name :	Dharmil Shah																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	intrusion																																		
Complain :	Site survey and client meeting																																		
Technician Comment :	GSM card and battery install demo given																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	GSM card and battery install demo given																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>02-02-2021 05:19:47</td><td>MayurYadav</td><td>Completed</td><td>GSM card and battery install demo given</td><td></td></tr><tr><td>01-02-2021 06:45:05</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>19-01-2021 01:19:27</td><td>MayurYadav</td><td>In Progress</td><td>survey done 4 magnetic door sensor 4 PIR sensor intrusion detection system 2 panic button 1 hooter</td><td></td></tr><tr><td>18-01-2021 07:16:03</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>18-01-2021 07:15:40</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	02-02-2021 05:19:47	MayurYadav	Completed	GSM card and battery install demo given		01-02-2021 06:45:05	MayurYadav	New		-	19-01-2021 01:19:27	MayurYadav	In Progress	survey done 4 magnetic door sensor 4 PIR sensor intrusion detection system 2 panic button 1 hooter		18-01-2021 07:16:03	MayurYadav	New		-	18-01-2021 07:15:40	MayurYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																															
02-02-2021 05:19:47	MayurYadav	Completed	GSM card and battery install demo given																																
01-02-2021 06:45:05	MayurYadav	New		-																															
19-01-2021 01:19:27	MayurYadav	In Progress	survey done 4 magnetic door sensor 4 PIR sensor intrusion detection system 2 panic button 1 hooter																																
18-01-2021 07:16:03	MayurYadav	New		-																															
18-01-2021 07:15:40	MayurYadav	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>14-08-2021 04:10:21</td><td>Siddhesh Chavan</td><td>Khar adidas intrusion panel inside one cancter loose please resolved permantly and panel cancter press and panel issue resolved</td></tr><tr><td>20-07-2021 06:43:21</td><td>MayurYadav</td><td>intrusion zone reconnection and bypass at panel side keep under observation</td></tr></tbody></table>					Date Time	Technician Name	Remark	14-08-2021 04:10:21	Siddhesh Chavan	Khar adidas intrusion panel inside one cancter loose please resolved permantly and panel cancter press and panel issue resolved	20-07-2021 06:43:21	MayurYadav	intrusion zone reconnection and bypass at panel side keep under observation																					
Date Time	Technician Name	Remark																																	
14-08-2021 04:10:21	Siddhesh Chavan	Khar adidas intrusion panel inside one cancter loose please resolved permantly and panel cancter press and panel issue resolved																																	
20-07-2021 06:43:21	MayurYadav	intrusion zone reconnection and bypass at panel side keep under observation																																	