Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

	1100.00.111							
Service Status De	etails : VE11221							
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob. No. :	9820536525							
Technician Name :	Ravi Rajbhar			echnician Mobile : 8080922965				
Ticket Type:	New Installation	Date & Time:		26-03-2024 11:46:21				
Vendor Details :								
Company Name/Client Name:	Vireshwar Heights	Customer's Mo	bile 9	le 9820536525		Name :	Dhiru Sir	
Address:								
Mumbai , , , , Ma	harashtra							
AMC Details :								
Expiry Date :	01-01-1970 05:30:00			ype:	pe:			
Product Name:	CCTV							
Complain :	cCTV survey to be done for aMC and Wifi camera need to install at dhiru bhai home							
Technician Comment :	dhiru sir home one wifi camera install with configuration done but SD card not install our side it's not recoding available and cmaera ok working user id - 9820684385 password - admin@123							
Complain Operator :	Desktop - Apurva Vajaria							
Remark:	dhiru sir home one wifi camera install with configuration done but SD card not install our side it's not recoding available and cmaera ok working user id - 9820684385 password - admin@123							
Status History :	Date Time	Technician Name	Status	atus Rem		ark	Sign	
	26-03-2024 01:58:07	Ravi Rajbhar	Complete	pleted dhiru sir home on install with config SD card not insta recoding available working user id password - admin		our side it's not and cmaera ok 820684385	lone but e it's not aera ok Aswito	
	26-03-2024 12:07:53	Ravi Rajbhar	New	łW			-	
Previous Complain	Date Time Technician Name Remark							
History:	16-03-2024 02:30:55	Atique Salmani	camera 12 floor change home a	New memory card installed and formatted recording on in wifi camera and dhiru bhai home cable trace and find out cable is on 12 floor duct also taging on cable and camera end BNC dc changed and set angel working ok of lobby view in dhiru bhai home also checked 1402 intercom comax vdp ringer issue need to changed basic phone client will confirm.				
	14-03-2024 11:25:09	1 11						