Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Det	cails : VE11615					
Priority:	Low					
Created By:	Admin - Apurva Vajaria					
Complaint Mob.	9820536525					
Technician Name :	Ravi Rajbhar		Technici	an Mobile :	8080922965	
Ticket Type :	Complain	Date & Time :	11-05-20	11-05-2024 01:41:55		
Vendor Details :	-					
Company Name/Client Name :	Vireshwar Heights	Customer's Mok	9820536	525	Name :	Dhiru Sir
Address:						
Mumbai , , , , Mał	narashtra					
AMC Details:			_			
Expiry Date :	01-01-1970 05:30:00		Type:	Type:		
Product Name:	Intercom					
Complain:	1102/403 - intercom	issue and camer	a bracket issue			
Technician Comment :	flat no. 1102 intercom issue resolved and ok working done flat no. 403 intercom issue resolved and ok working done check both flat junction site cable					
Complain Operator :	Desktop - Apurva Va	ajaria				
Remark:	flat no. 1102 interco				403 intercom is	ssue resolved
Status History :	Date Time	Technician Name	Status	R	Remark	
	15-05-2024 03:02:21	Ravi Rajbhar	Completed	flat no. 1102 intercom issue resolved and ok working done flat no. 403 intercom issue resolved and ok working done check both flat junction site cable		Stype
	15-05-2024 10:53:59	Ravi Rajbhar	New			-
	14-05-2024 11:35:11	Ravi Rajbhar	New			-
	11-05-2024 01:51:21	Ravi Rajbhar	Work Pending	and 403 inte but reception working nee- visit and can	m issue resolve rcom working n to flat call not d to check next nera 4*4 box t visit need to	Asma
	11-05-2024 01:42:02	Ravi Rajbhar	New			-

Previous Complain History:

Date Time	Technician Name	Remark
22-05-2024 11:31:19		
10-04-2024 11:26:51	PravinJagade	Wifi camera installation done working ok. Motion detection properly working.