




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2993																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9820536525																								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																					
Ticket Type :	Complain	Date & Time :	17-04-2021 11:12:03																						
Vendor Details :																									
Company Name/Client Name :	Vireshwar Heights	Customer's Mobile :	9820536525	Name :	Dhiru Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	VDP																								
Complain :	video issue from lobby panel																								
Technician Comment :	1301 dhruv sir lobby camera issue resolved and ok working done (flat to duct cable check and duct to video distributor ground floor) duct cable cut also and cable joiding and new video distributor 4 Ch install work completed																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	1301 dhruv sir lobby camera issue resolved and ok working done (flat to duct cable check and duct to video distributor ground floor) duct cable cut also and cable joiding and new video distributor 4 Ch install work completed																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>17-04-2021 06:59:08</td><td>Ravi Rajbhar</td><td>Completed</td><td>1301 dhruv sir lobby camera issue resolved and ok working done (flat to duct cable check and duct to video distributor ground floor) duct cable cut also and cable joiding and new video distributor 4 Ch install work completed</td><td></td></tr><tr><td>17-04-2021 11:12:15</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>17-04-2021 11:12:03</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	17-04-2021 06:59:08	Ravi Rajbhar	Completed	1301 dhruv sir lobby camera issue resolved and ok working done (flat to duct cable check and duct to video distributor ground floor) duct cable cut also and cable joiding and new video distributor 4 Ch install work completed		17-04-2021 11:12:15	Ravi Rajbhar	New		-	17-04-2021 11:12:03	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
17-04-2021 06:59:08	Ravi Rajbhar	Completed	1301 dhruv sir lobby camera issue resolved and ok working done (flat to duct cable check and duct to video distributor ground floor) duct cable cut also and cable joiding and new video distributor 4 Ch install work completed																						
17-04-2021 11:12:15	Ravi Rajbhar	New		-																					
17-04-2021 11:12:03	Ravi Rajbhar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>07-08-2023 08:53:09</td><td>Atique Salmani</td><td>Intercom installation + with acrylic sheet installed intercom with acrylic sheet working ok</td></tr><tr><td>11-07-2023 05:11:59</td><td>Atique Salmani</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	07-08-2023 08:53:09	Atique Salmani	Intercom installation + with acrylic sheet installed intercom with acrylic sheet working ok	11-07-2023 05:11:59	Atique Salmani												
Date Time	Technician Name	Remark																							
07-08-2023 08:53:09	Atique Salmani	Intercom installation + with acrylic sheet installed intercom with acrylic sheet working ok																							
11-07-2023 05:11:59	Atique Salmani																								

