

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8029																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9820536525																								
Technician Name :	Santosh Pathak		Technician Mobile :	8080922980																					
Ticket Type :	Complain	Date & Time :	04-04-2023 10:11:19																						
Vendor Details :																									
Company Name/Client Name :	Vireshwar Heights	Customer's Mobile :	9820536525	Name :	Dhiru Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	Intercom																								
Complain :	flat no 504 need to do connection and flat no 301 need to install new phone																								
Technician Comment :																									
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	Kalpesh - flat no. 301 beete1 telephone installed done collect 575/- cash 504 - ok																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>11-04-2023 03:45:01</td><td>SantoshPathak</td><td>Completed</td><td></td><td>-</td></tr><tr><td>06-04-2023 11:03:06</td><td>SantoshPathak</td><td>New</td><td></td><td>-</td></tr><tr><td>04-04-2023 10:11:31</td><td>SantoshPathak</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	11-04-2023 03:45:01	SantoshPathak	Completed		-	06-04-2023 11:03:06	SantoshPathak	New		-	04-04-2023 10:11:31	SantoshPathak	New		-
Date Time	Technician Name	Status	Remark	Sign																					
11-04-2023 03:45:01	SantoshPathak	Completed		-																					
06-04-2023 11:03:06	SantoshPathak	New		-																					
04-04-2023 10:11:31	SantoshPathak	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>24-03-2023 10:26:34</td><td>SantoshPathak</td><td>203 - Beetel wallmount phone installed done</td></tr><tr><td>16-03-2023 11:12:53</td><td>SantoshPathak</td><td>16.03.2023 Kalpesh visited - Beetel wallmount new phone installed 501, 503, 302, 201, 204 15.03.2023 Kalpesh visited - 303-new beetel phone installed, 301- VDP faulty, 302 - VDP faulty 602 - OK, 1202 - New phone required, 202 - ok, 201 -vdp faulty, 501- new phone required, 1301 -ok, 1101-lock, 902 - lock, 702 - ok, 804 - line ok phone not connect, 502 - ok, 503 - phone faulty reset box connect, 504 - vdp faulty, 401 - lock, 402 vdp faulty, 1204 - ok, 901 - ok, 802 - new phone required</td></tr></tbody></table>					Date Time	Technician Name	Remark	24-03-2023 10:26:34	SantoshPathak	203 - Beetel wallmount phone installed done	16-03-2023 11:12:53	SantoshPathak	16.03.2023 Kalpesh visited - Beetel wallmount new phone installed 501, 503, 302, 201, 204 15.03.2023 Kalpesh visited - 303-new beetel phone installed, 301- VDP faulty, 302 - VDP faulty 602 - OK, 1202 - New phone required, 202 - ok, 201 -vdp faulty, 501- new phone required, 1301 -ok, 1101-lock, 902 - lock, 702 - ok, 804 - line ok phone not connect, 502 - ok, 503 - phone faulty reset box connect, 504 - vdp faulty, 401 - lock, 402 vdp faulty, 1204 - ok, 901 - ok, 802 - new phone required											
Date Time	Technician Name	Remark																							
24-03-2023 10:26:34	SantoshPathak	203 - Beetel wallmount phone installed done																							
16-03-2023 11:12:53	SantoshPathak	16.03.2023 Kalpesh visited - Beetel wallmount new phone installed 501, 503, 302, 201, 204 15.03.2023 Kalpesh visited - 303-new beetel phone installed, 301- VDP faulty, 302 - VDP faulty 602 - OK, 1202 - New phone required, 202 - ok, 201 -vdp faulty, 501- new phone required, 1301 -ok, 1101-lock, 902 - lock, 702 - ok, 804 - line ok phone not connect, 502 - ok, 503 - phone faulty reset box connect, 504 - vdp faulty, 401 - lock, 402 vdp faulty, 1204 - ok, 901 - ok, 802 - new phone required																							