## Vallabh Enterprises

**Regd. Office** : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE1550 **Priority** : High **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9980471704 **No. : Technician Name** Mayur Yadav **Technician Mobile** 8411951301 Complain Date & Time : 13-07-2020 12:50:15 **Ticket Type :** Vendor Details : **Concentrix Services** Customer's Mobile 9980471704 Dinesh Company Name : Name/Client Name India Pvt. Ltd--Menon Ecospace4a Address : bangalore,,,560029, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV Remote Playback CCTV Application Is not working at Eco space 4A location. **Complain**: remote playback application problem solve new updated iVMS software installed Technician **Comment**: Complain Desktop - Apurva Vajaria **Operator** : **Remark** : remote playback application problem solve new updated iVMS software installed **Status History :** Technician Name **Date Time** Status Remark Sign 14-07-2020 02:08:04 MayurYadav Completed remote playback application problem solve new updated iVMS software installed 13-07-2020 12:50:24 MayurYadav New 13-07-2020 12:50:16 MayurYadav New Previous **Date Time Technician Name** Remark **Complain History** 08-11-2020 01:10:24 checked the server controller the cable was disconnected. Now both the door working fine 27-10-2020 10:12:46 YashDoshi Issue has been resolved as it was because of internal issue with CAS and the same was resolved by CAS team.