







# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE11277</b>																														
<b>Priority :</b>	Low																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	9619474819																													
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																										
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	01-04-2024 02:24:03																											
<b>Vendor Details :</b>																														
<b>Company Name/Client Name :</b>	Shree Ram Welfare Society High School	<b>Customer's Mobile :</b>	9619474819	<b>Name :</b>	Dinesh Sir																									
<b>Address :</b>																														
Mumbai , , , 400058 , Maharashtra																														
<b>AMC Details :</b>																														
<b>Expiry Date :</b>	31-05-2021 12:00:00		<b>Type :</b>	Non-Comprehensive																										
<b>Product Name :</b>	CCTV																													
<b>Complain :</b>	computer lab 1st floor camera need to check																													
<b>Technician Comment :</b>	1st floor computer room one cmaera repaired and return with install and ok working done																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	1st floor computer room one cmaera repaired and return with install and ok working done																													
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>12-04-2024 03:26:22</td><td>Ravi Rajbhar</td><td>Completed</td><td>1st floor computer room one cmaera repaired and return with install and ok working done</td><td></td></tr><tr><td>12-04-2024 12:24:55</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>01-04-2024 02:36:24</td><td>Ravi Rajbhar</td><td>Work Pending</td><td>1 camera faulty computer lab 1st floor camera collect</td><td></td></tr><tr><td>01-04-2024 02:24:11</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	12-04-2024 03:26:22	Ravi Rajbhar	Completed	1st floor computer room one cmaera repaired and return with install and ok working done		12-04-2024 12:24:55	Ravi Rajbhar	New		-	01-04-2024 02:36:24	Ravi Rajbhar	Work Pending	1 camera faulty computer lab 1st floor camera collect		01-04-2024 02:24:11	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																										
12-04-2024 03:26:22	Ravi Rajbhar	Completed	1st floor computer room one cmaera repaired and return with install and ok working done																											
12-04-2024 12:24:55	Ravi Rajbhar	New		-																										
01-04-2024 02:36:24	Ravi Rajbhar	Work Pending	1 camera faulty computer lab 1st floor camera collect																											
01-04-2024 02:24:11	Ravi Rajbhar	New		-																										
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>30-03-2024 10:08:45</td><td>Sonu Kumar</td><td>Cctv intercom ppm done 1 ip camera off issue resolved working ok and 2 nvr camera naming done</td></tr><tr><td>29-02-2024 02:14:13</td><td>Atique Salmani</td><td>Till 1st floor line working ok cable cut from midway so security line was not working find the cable 1st floor to security cabin cabling need to do 40/50 meter cable approx also tagging on 1st floor stair case 111 is extaintion nmbr .</td></tr></tbody></table>					Date Time	Technician Name	Remark	30-03-2024 10:08:45	Sonu Kumar	Cctv intercom ppm done 1 ip camera off issue resolved working ok and 2 nvr camera naming done	29-02-2024 02:14:13	Atique Salmani	Till 1st floor line working ok cable cut from midway so security line was not working find the cable 1st floor to security cabin cabling need to do 40/50 meter cable approx also tagging on 1st floor stair case 111 is extaintion nmbr .																
Date Time	Technician Name	Remark																												
30-03-2024 10:08:45	Sonu Kumar	Cctv intercom ppm done 1 ip camera off issue resolved working ok and 2 nvr camera naming done																												
29-02-2024 02:14:13	Atique Salmani	Till 1st floor line working ok cable cut from midway so security line was not working find the cable 1st floor to security cabin cabling need to do 40/50 meter cable approx also tagging on 1st floor stair case 111 is extaintion nmbr .																												