




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE12558																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9619474819																			
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																
Ticket Type :	Complain	Date & Time :	28-08-2024 11:40:07																	
Vendor Details :																				
Company Name/Client Name :	Shree Ram Welfare Society High School	Customer's Mobile :	9619474819	Name :	Dinesh Sir															
Address :																				
Mumbai , , , 400058 , Maharashtra																				
AMC Details :																				
Expiry Date :	31-05-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	1)2nd floor class no. 8 camera need to reinstall 2)1st floor class no. 4th c new camera need to install																			
Technician Comment :	2nd floor class room 8 old cmaera reinstall and ok working done and 1st floor class room 4 new cmaera install but poe switch side pending bcz poe switch all port full and main gate two cmaera angle set and cmaera main entry above temporary going on client side two cmaera cable check 2nd floor hall and 1st floor class room 4 both cabling breck																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	2nd floor class room 8 old cmaera reinstall and ok working done and 1st floor class room 4 new cmaera install but poe switch side pending bcz poe switch all port full and main gate two cmaera angle set and cmaera main entry above temporary going on client side two cmaera cable check 2nd floor hall and 1st floor class room 4 both cabling breck																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>29-08-2024 02:24:38</td><td>Ravi Rajbhar</td><td>Completed</td><td>2nd floor class room 8 old cmaera reinstall and ok working done and 1st floor class room 4 new cmaera install but poe switch side pending bcz poe switch all port full and main gate two cmaera angle set and cmaera main entry above temporary going on client side two cmaera cable check 2nd floor hall and 1st floor class room 4 both cabling breck</td><td></td></tr><tr><td>28-08-2024 06:55:54</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	29-08-2024 02:24:38	Ravi Rajbhar	Completed	2nd floor class room 8 old cmaera reinstall and ok working done and 1st floor class room 4 new cmaera install but poe switch side pending bcz poe switch all port full and main gate two cmaera angle set and cmaera main entry above temporary going on client side two cmaera cable check 2nd floor hall and 1st floor class room 4 both cabling breck		28-08-2024 06:55:54	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
29-08-2024 02:24:38	Ravi Rajbhar	Completed	2nd floor class room 8 old cmaera reinstall and ok working done and 1st floor class room 4 new cmaera install but poe switch side pending bcz poe switch all port full and main gate two cmaera angle set and cmaera main entry above temporary going on client side two cmaera cable check 2nd floor hall and 1st floor class room 4 both cabling breck																	
28-08-2024 06:55:54	Ravi Rajbhar	New		-																

Previous Complain History :	Date Time	Technician Name	Remark
	16-11-2024 11:19:25	ManojPolekar	Ground floor 2 camera installed and 1 st floor 3 cameras installed now all cameras working normally
	14-11-2024 10:53:05		