

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14556															
Priority :	Low														
Created By :	Admin - Apurva Vajaria														
Complaint Mob. No. :	9820858158														
Technician Name :	Pravin Jagade		Technician Mobile :	7262044153											
Ticket Type :	Complain	Date & Time :	22-04-2025 10:41:16												
Vendor Details :															
Company Name/Client Name :	Vedantaa Institute Of Academic(Shrenik Bhai)	Customer's Mobile :	9820858158	Name :	Dipesh Sir										
Address :															
Mumbai , , , , Maharashtra															
AMC Details :															
Expiry Date :	01-01-1970 05:30:00		Type :												
Product Name :	Access														
Complain :	1)New computer software install 2)both turnstile locking issue 3)Upper side turnstile locking issue and face reader not working some screws need to send														
Technician Comment :															
Complain Operator :	Desktop - Apurva Vajaria														
Remark :															
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>22-04-2025 10:41:41</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	22-04-2025 10:41:41	PravinJagade	New		-
Date Time	Technician Name	Status	Remark	Sign											
22-04-2025 10:41:41	PravinJagade	New		-											
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>18-06-2025 10:38:20</td><td>Ravi Rajbhar</td><td>First floor 1)one turnstile it is getting stuck issue resolved and ok working done 2)one turnstile in out both magnetic lock issue and both lock remove and take to office 3)biomax web software licence key update done Ground floor orbit mess 1)Biometric adapter change and faulty handover to client 2)1 turnstile magnetic lock change against faulty 3)4 Pin lan cable change all ok working done work completed</td></tr><tr><td>03-05-2025 10:17:58</td><td>Ravi Rajbhar</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	18-06-2025 10:38:20	Ravi Rajbhar	First floor 1)one turnstile it is getting stuck issue resolved and ok working done 2)one turnstile in out both magnetic lock issue and both lock remove and take to office 3)biomax web software licence key update done Ground floor orbit mess 1)Biometric adapter change and faulty handover to client 2)1 turnstile magnetic lock change against faulty 3)4 Pin lan cable change all ok working done work completed	03-05-2025 10:17:58	Ravi Rajbhar		
Date Time	Technician Name	Remark													
18-06-2025 10:38:20	Ravi Rajbhar	First floor 1)one turnstile it is getting stuck issue resolved and ok working done 2)one turnstile in out both magnetic lock issue and both lock remove and take to office 3)biomax web software licence key update done Ground floor orbit mess 1)Biometric adapter change and faulty handover to client 2)1 turnstile magnetic lock change against faulty 3)4 Pin lan cable change all ok working done work completed													
03-05-2025 10:17:58	Ravi Rajbhar														