







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15232																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9870202066																								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																					
Ticket Type :	Complain	Date & Time :	10-07-2025 12:16:35																						
Vendor Details :																									
Company Name/Client Name :	Bhupendra Mhatre	Customer's Mobile :	9870202066	Name :	Eksar Koliwadi Mitra Mandal (agri) Smashan Bhoomi																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	1 camera showing error network is unreachable																								
Technician Comment :	1 bullet ip camera showing off so chek this there is issue in cat 6 cable so required new cat 6 cabling approx 100 metr and camera remooved and kept it in nvr rack .																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	1 bullet ip camera showing off so chek this there is issue in cat 6 cable so required new cat 6 cabling approx 100 metr and camera remooved and kept it in nvr rack .																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-07-2025 03:46:34</td><td>Atique Salmani</td><td>Awaiting Spares</td><td>1 bullet ip camera showing off so chek this there is issue in cat 6 cable so required new cat 6 cabling approx 100 metr and camera remooved and kept it in nvr rack .</td><td></td></tr><tr><td>10-07-2025 03:46:33</td><td>Atique Salmani</td><td>Awaiting Spares</td><td>1 bullet ip camera showing off so chek this there is issue in cat 6 cable so required new cat 6 cabling approx 100 metr and camera remooved and kept it in nvr rack .</td><td></td></tr><tr><td>10-07-2025 12:16:55</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-07-2025 03:46:34	Atique Salmani	Awaiting Spares	1 bullet ip camera showing off so chek this there is issue in cat 6 cable so required new cat 6 cabling approx 100 metr and camera remooved and kept it in nvr rack .		10-07-2025 03:46:33	Atique Salmani	Awaiting Spares	1 bullet ip camera showing off so chek this there is issue in cat 6 cable so required new cat 6 cabling approx 100 metr and camera remooved and kept it in nvr rack .		10-07-2025 12:16:55	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
10-07-2025 03:46:34	Atique Salmani	Awaiting Spares	1 bullet ip camera showing off so chek this there is issue in cat 6 cable so required new cat 6 cabling approx 100 metr and camera remooved and kept it in nvr rack .																						
10-07-2025 03:46:33	Atique Salmani	Awaiting Spares	1 bullet ip camera showing off so chek this there is issue in cat 6 cable so required new cat 6 cabling approx 100 metr and camera remooved and kept it in nvr rack .																						
10-07-2025 12:16:55	Atique Salmani	New		-																					

Previous Complain History :	Date Time	Technician Name	Remark
	06-08-2025 10:26:12	PravinJagade	1 camera offline issue resolve done. Connector not proper punch. New connector punch. All canera proper working done.
	01-08-2025 11:03:54	SantoshPathak	cabling work done by tukaram