







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE10756																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9967289792																																		
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																															
Ticket Type :	Complain	Date & Time :	05-02-2024 11:45:19																																
Vendor Details :																																			
Company Name/Client Name :	Zenworld Wing D CHS Ltd	Customer's Mobile :	9967289792	Name :	Ganesh Sir																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	CCTV																																		
Complain :	lift no. 2 camera not working																																		
Technician Comment :	d wing lift no. 2 cmaera off line issue resolved and ok working done access point reset and reconfigure done and ok working done																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	d wing lift no. 2 cmaera off line issue resolved and ok working done access point reset and reconfigure done and ok working done																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>15-02-2024 02:15:22</td><td>Ravi Rajbhar</td><td>Completed</td><td>d wing lift no. 2 cmaera off line issue resolved and ok working done access point reset and reconfigure done and ok working done</td><td></td></tr><tr><td>15-02-2024 10:29:02</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>09-02-2024 11:57:26</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>06-02-2024 10:00:08</td><td>Ravi Rajbhar</td><td>Work Pending</td><td>When lift go on 22 floor when camera showing network disconnected bec it's range issue so extender receiver need to be installed same location and observe.</td><td></td></tr><tr><td>06-02-2024 09:56:29</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	15-02-2024 02:15:22	Ravi Rajbhar	Completed	d wing lift no. 2 cmaera off line issue resolved and ok working done access point reset and reconfigure done and ok working done		15-02-2024 10:29:02	Ravi Rajbhar	New		-	09-02-2024 11:57:26	Ravi Rajbhar	New		-	06-02-2024 10:00:08	Ravi Rajbhar	Work Pending	When lift go on 22 floor when camera showing network disconnected bec it's range issue so extender receiver need to be installed same location and observe.		06-02-2024 09:56:29	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																															
15-02-2024 02:15:22	Ravi Rajbhar	Completed	d wing lift no. 2 cmaera off line issue resolved and ok working done access point reset and reconfigure done and ok working done																																
15-02-2024 10:29:02	Ravi Rajbhar	New		-																															
09-02-2024 11:57:26	Ravi Rajbhar	New		-																															
06-02-2024 10:00:08	Ravi Rajbhar	Work Pending	When lift go on 22 floor when camera showing network disconnected bec it's range issue so extender receiver need to be installed same location and observe.																																
06-02-2024 09:56:29	Ravi Rajbhar	New		-																															

Previous Complain History :	Date Time	Technician Name	Remark
	15-01-2024 10:34:28	Anil Yadav	Tp link transmitter installed working fine.