







# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE16033</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9820434743																								
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																					
<b>Ticket Type :</b>	New Installation	<b>Date &amp; Time :</b>	16-10-2025 10:57:05																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>		<b>Customer's Mobile :</b>	9820434743	<b>Name :</b>	Hardik Bhai Architect																				
<b>Address :</b>																									
Mumbai , , , 400075 , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																						
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	1)Old Camera need to install. 2) Intercom need to install. 3) Biometric access installation.																								
<b>Technician Comment :</b>	4 camera install and 308 epbax system install with 5 6 phone connect and one co line connect All ok working done																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	4 camera install and 308 epbax system install with 5 6 phone connect and one co line connect All ok working done																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>16-10-2025 04:44:12</td><td>Ravi Rajbhar</td><td>Completed</td><td>4 camera install and 308 epbax system install with 5 6 phone connect and one co line connect All ok working done</td><td></td></tr><tr><td>16-10-2025 04:44:11</td><td>Ravi Rajbhar</td><td>Completed</td><td>4 camera install and 308 epbax system install with 5 6 phone connect and one co line connect All ok working done</td><td></td></tr><tr><td>16-10-2025 10:57:22</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	16-10-2025 04:44:12	Ravi Rajbhar	Completed	4 camera install and 308 epbax system install with 5 6 phone connect and one co line connect All ok working done		16-10-2025 04:44:11	Ravi Rajbhar	Completed	4 camera install and 308 epbax system install with 5 6 phone connect and one co line connect All ok working done		16-10-2025 10:57:22	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
16-10-2025 04:44:12	Ravi Rajbhar	Completed	4 camera install and 308 epbax system install with 5 6 phone connect and one co line connect All ok working done																						
16-10-2025 04:44:11	Ravi Rajbhar	Completed	4 camera install and 308 epbax system install with 5 6 phone connect and one co line connect All ok working done																						
16-10-2025 10:57:22	Ravi Rajbhar	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>14-10-2025 11:58:43</td><td>Atique Salmani</td><td>4 channel nvr installation done and 4 channel poe switch installed biometric with all no touch bolt lock and 4 dome camera installation done but 2 on 2 cable find out painting from electrician end and intercom all painting cable didn't find out from electrician side .</td></tr></tbody></table>					Date Time	Technician Name	Remark	14-10-2025 11:58:43	Atique Salmani	4 channel nvr installation done and 4 channel poe switch installed biometric with all no touch bolt lock and 4 dome camera installation done but 2 on 2 cable find out painting from electrician end and intercom all painting cable didn't find out from electrician side .														
Date Time	Technician Name	Remark																							
14-10-2025 11:58:43	Atique Salmani	4 channel nvr installation done and 4 channel poe switch installed biometric with all no touch bolt lock and 4 dome camera installation done but 2 on 2 cable find out painting from electrician end and intercom all painting cable didn't find out from electrician side .																							