




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE6898</b>																														
<b>Priority :</b>	Low																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	9768277860																													
<b>Technician Name :</b>	Siddhesh Chavan		<b>Technician Mobile :</b>	8080922985																										
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	21-11-2022 11:13:00																											
<b>Vendor Details :</b>																														
Company Name/Client Name :	Mother Mary Junior Collage Nalasopara East	Customer's Mobile :	9768277860	Name :	Harish Karaya																									
<b>Address :</b>																														
Mumbai , , , , Maharashtra																														
<b>AMC Details :</b>																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
<b>Product Name :</b>	CCTV																													
<b>Complain :</b>	CCTV survey need to do																													
<b>Technician Comment :</b>	mother Mary junior college ground floor 2 dvr check, dvr no 1 HDD error need to check 2 camera pending and survey pending																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	mother Mary junior college ground floor 2 dvr check, dvr no 1 HDD error need to check 2 camera pending and survey pending																													
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>24-11-2022 10:11:01</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>23-11-2022 11:45:57</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>21-11-2022 12:44:23</td><td>Siddhesh Chavan</td><td>Work Pending</td><td>mother Mary junior college ground floor 2 dvr check, dvr no 1 HDD error need to check 2 camera pending and survey pending</td><td></td></tr><tr><td>21-11-2022 11:13:08</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	24-11-2022 10:11:01	Siddhesh Chavan	New		-	23-11-2022 11:45:57	Siddhesh Chavan	New		-	21-11-2022 12:44:23	Siddhesh Chavan	Work Pending	mother Mary junior college ground floor 2 dvr check, dvr no 1 HDD error need to check 2 camera pending and survey pending		21-11-2022 11:13:08	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																										
24-11-2022 10:11:01	Siddhesh Chavan	New		-																										
23-11-2022 11:45:57	Siddhesh Chavan	New		-																										
21-11-2022 12:44:23	Siddhesh Chavan	Work Pending	mother Mary junior college ground floor 2 dvr check, dvr no 1 HDD error need to check 2 camera pending and survey pending																											
21-11-2022 11:13:08	Siddhesh Chavan	New		-																										
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>19-07-2023 10:56:31</td><td>Sonu Kumar</td><td>Old building and new building fees counter common and all ready fees counter camera install</td></tr><tr><td>19-07-2023 10:47:14</td><td>Sonu Kumar</td><td>Camera cannot be installed on the 4th floor due to water leakage. Camera cannot be installed in room no. 306 as there is no light.</td></tr></tbody></table>					Date Time	Technician Name	Remark	19-07-2023 10:56:31	Sonu Kumar	Old building and new building fees counter common and all ready fees counter camera install	19-07-2023 10:47:14	Sonu Kumar	Camera cannot be installed on the 4th floor due to water leakage. Camera cannot be installed in room no. 306 as there is no light.																
Date Time	Technician Name	Remark																												
19-07-2023 10:56:31	Sonu Kumar	Old building and new building fees counter common and all ready fees counter camera install																												
19-07-2023 10:47:14	Sonu Kumar	Camera cannot be installed on the 4th floor due to water leakage. Camera cannot be installed in room no. 306 as there is no light.																												