




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE8897</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9768277860																								
<b>Technician Name :</b>	Sonu Kumar		<b>Technician Mobile :</b>	8454016444																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	19-07-2023 10:47:14																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Mother Mary Junior Collage Nalasopara East	<b>Customer's Mobile :</b>	9768277860	<b>Name :</b>	Harish Karaya																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																						
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	4th floor staircase side camera need to install against faulty																								
<b>Technician Comment :</b>	Camera cannot be installed on the 4th floor due to water leakage. Camera cannot be installed in room no. 306 as there is no light.																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	Camera cannot be installed on the 4th floor due to water leakage. Camera cannot be installed in room no. 306 as there is no light.																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>24-07-2023 12:05:02</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr><tr><td>19-07-2023 01:40:17</td><td>Sonu Kumar</td><td>Client Side</td><td>Camera cannot be installed on the 4th floor due to water leakage. Camera cannot be installed in room no. 306 as there is no light.</td><td></td></tr><tr><td>19-07-2023 10:47:22</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	24-07-2023 12:05:02	Sonu Kumar	New		-	19-07-2023 01:40:17	Sonu Kumar	Client Side	Camera cannot be installed on the 4th floor due to water leakage. Camera cannot be installed in room no. 306 as there is no light.		19-07-2023 10:47:22	Sonu Kumar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
24-07-2023 12:05:02	Sonu Kumar	New		-																					
19-07-2023 01:40:17	Sonu Kumar	Client Side	Camera cannot be installed on the 4th floor due to water leakage. Camera cannot be installed in room no. 306 as there is no light.																						
19-07-2023 10:47:22	Sonu Kumar	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>19-07-2023 10:56:31</td><td>Sonu Kumar</td><td>Old building and new building fees counter common and all ready fees counter camera install</td></tr><tr><td>26-06-2023 10:34:45</td><td>Sonu Kumar</td><td>4th floor 403 camera angle set and satir see camer a faulty camera collect and 3rd floor 304 302 camera angle set and 1st floor 4-5 camera distance issue resolved working ok and ground floor 8chanl smps faulty and 2 new 4chanal power supply install all camera working ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	19-07-2023 10:56:31	Sonu Kumar	Old building and new building fees counter common and all ready fees counter camera install	26-06-2023 10:34:45	Sonu Kumar	4th floor 403 camera angle set and satir see camer a faulty camera collect and 3rd floor 304 302 camera angle set and 1st floor 4-5 camera distance issue resolved working ok and ground floor 8chanl smps faulty and 2 new 4chanal power supply install all camera working ok											
Date Time	Technician Name	Remark																							
19-07-2023 10:56:31	Sonu Kumar	Old building and new building fees counter common and all ready fees counter camera install																							
26-06-2023 10:34:45	Sonu Kumar	4th floor 403 camera angle set and satir see camer a faulty camera collect and 3rd floor 304 302 camera angle set and 1st floor 4-5 camera distance issue resolved working ok and ground floor 8chanl smps faulty and 2 new 4chanal power supply install all camera working ok																							