## Vallabh Enterprises

**Regd. Office** : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE13182 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9822193699 **No. : Technician Name :** Ravi Rajbhar **Technician Mobile** 8080922965 : Complain Date & Time : 06-11-2024 10:39:10 **Ticket Type :** Vendor Details : Customer's Mobile 9822193699 Harsh Buildcon Name : Harish Sir Company Name/Client Name : Address : shahapur , , , , Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** Access **Complain**: door access Key fob need to change One new transmeter receiver installe and ok working done with wireless remote two **Technician** hondover to client **Comment** : **Complain Operator** Desktop - Apurva Vajaria **Remark** : One new transmeter receiver installe and ok working done with wireless remote two hondover to client **Status History : Date Time Technician Name** Status Remark Sign 06-11-2024 Ravi Rajbhar Completed One new transmeter 11:03:22 receiver installe and ok working done with wireless remote two hondover to client 06-11-2024 Ravi Rajbhar New 10:39:24 **Previous Complain Date Time Technician Name** Remark **History** : 11-08-2020 12:49:30 SantoshPathak reconnection done and now it's working fine