

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15426																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	8879250068																													
Technician Name :	Pravin Jagade		Technician Mobile :	7262044153																										
Ticket Type :	Complain	Date & Time :	30-07-2025 12:15:59																											
Vendor Details :																														
Company Name/Client Name :	Rughani Villa Jaswanti Owner Home	Customer's Mobile :	8879250068	Name :	Hemant Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	Intercom																													
Complain :	13 and 14th floor intercom issue																													
Technician Comment :	14 floor intercom issue resolve working done. 13 floor intercom not check not allowed.																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	14 floor intercom issue resolve working done. 13 floor intercom not check not allowed.																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>30-07-2025 12:24:42</td><td>PravinJagade</td><td>Completed</td><td></td><td>-</td></tr><tr><td>30-07-2025 12:22:06</td><td>PravinJagade</td><td>Work Pending</td><td>14 floor intercom issue resolve working done. 13 floor intercom not check not allowed.</td><td></td></tr><tr><td>30-07-2025 12:22:06</td><td>PravinJagade</td><td>Work Pending</td><td>14 floor intercom issue resolve working done. 13 floor intercom not check not allowed.</td><td></td></tr><tr><td>30-07-2025 12:16:07</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	30-07-2025 12:24:42	PravinJagade	Completed		-	30-07-2025 12:22:06	PravinJagade	Work Pending	14 floor intercom issue resolve working done. 13 floor intercom not check not allowed.		30-07-2025 12:22:06	PravinJagade	Work Pending	14 floor intercom issue resolve working done. 13 floor intercom not check not allowed.		30-07-2025 12:16:07	PravinJagade	New		-
Date Time	Technician Name	Status	Remark	Sign																										
30-07-2025 12:24:42	PravinJagade	Completed		-																										
30-07-2025 12:22:06	PravinJagade	Work Pending	14 floor intercom issue resolve working done. 13 floor intercom not check not allowed.																											
30-07-2025 12:22:06	PravinJagade	Work Pending	14 floor intercom issue resolve working done. 13 floor intercom not check not allowed.																											
30-07-2025 12:16:07	PravinJagade	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>04-08-2025 01:09:29</td><td>SantoshPathak</td><td>After fiber optical cabling done Gulambhai visited on 02.08.2025 and splicing work done and all intercom issue resolved.</td></tr><tr><td>30-07-2025 10:23:52</td><td>PravinJagade</td><td>Old exit switch not working. New exit switch proper working done. Work complete.</td></tr></tbody></table>					Date Time	Technician Name	Remark	04-08-2025 01:09:29	SantoshPathak	After fiber optical cabling done Gulambhai visited on 02.08.2025 and splicing work done and all intercom issue resolved.	30-07-2025 10:23:52	PravinJagade	Old exit switch not working. New exit switch proper working done. Work complete.																
Date Time	Technician Name	Remark																												
04-08-2025 01:09:29	SantoshPathak	After fiber optical cabling done Gulambhai visited on 02.08.2025 and splicing work done and all intercom issue resolved.																												
30-07-2025 10:23:52	PravinJagade	Old exit switch not working. New exit switch proper working done. Work complete.																												