

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE1165																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	8451099978																								
Technician Name :	Zainul Shaikh		Technician Mobile :	8080922971																					
Ticket Type :	Complain	Date & Time :	17-02-2020 04:37:27																						
Vendor Details :																									
Company Name/Client Name :	Dev Research Centre	Customer's Mobile :	8451099978	Name :	Hitesh Doshi																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	12-09-2020 12:00:00		Type :	Comprehensive																					
Product Name :	Access																								
Complain :	unable to connect device																								
Technician Comment :																									
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	online done and given support and work completed Confirm by hitesh sir work done																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>20-02-2020 10:05:18</td><td>ZainulShaikh</td><td>Completed</td><td></td><td>-</td></tr><tr><td>20-02-2020 10:04:42</td><td>ZainulShaikh</td><td>New</td><td></td><td>-</td></tr><tr><td>17-02-2020 04:37:28</td><td>ZainulShaikh</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	20-02-2020 10:05:18	ZainulShaikh	Completed		-	20-02-2020 10:04:42	ZainulShaikh	New		-	17-02-2020 04:37:28	ZainulShaikh	New		-
Date Time	Technician Name	Status	Remark	Sign																					
20-02-2020 10:05:18	ZainulShaikh	Completed		-																					
20-02-2020 10:04:42	ZainulShaikh	New		-																					
17-02-2020 04:37:28	ZainulShaikh	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>14-02-2020 09:58:15</td><td>ZainulShaikh</td><td>main supply plug in direction change. resistor connect in panel side. now under observation</td></tr><tr><td>10-02-2020 02:26:10</td><td>Atique Salmani</td><td>on battery conector full fungus and from transformar loose contact all issue resolved also checked smoke detector by smoke working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	14-02-2020 09:58:15	ZainulShaikh	main supply plug in direction change. resistor connect in panel side. now under observation	10-02-2020 02:26:10	Atique Salmani	on battery conector full fungus and from transformar loose contact all issue resolved also checked smoke detector by smoke working ok.											
Date Time	Technician Name	Remark																							
14-02-2020 09:58:15	ZainulShaikh	main supply plug in direction change. resistor connect in panel side. now under observation																							
10-02-2020 02:26:10	Atique Salmani	on battery conector full fungus and from transformar loose contact all issue resolved also checked smoke detector by smoke working ok.																							