




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE1801</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	8451099978																								
<b>Technician Name :</b>	Yasin Shaikh		<b>Technician Mobile :</b>	8689802313																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	08-09-2020 10:43:10																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Dev Research Centre	Customer's Mobile :	8451099978	Name :	Hitesh Doshi																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	06-06-2021 12:00:00		Type :	Comprehensive																					
<b>Product Name :</b>	EPABX																								
<b>Complain :</b>	2 extension issue smoke sensor false alarm access door issue																								
<b>Technician Comment :</b>	intercom issues solve and fire alarm issue solved by panel reset access door power supply faulty by supply change work completed																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	intercom issues solve and fire alarm issue solved by panel reset access door power supply faulty by supply change work completed																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>08-09-2020 11:06:29</td><td>YasinShaikh</td><td>Completed</td><td>intercom issues solve and fire alarm issue solved by panel reset access door power supply faulty by supply change work completed</td><td></td></tr><tr><td>08-09-2020 10:43:22</td><td>YasinShaikh</td><td>New</td><td></td><td>-</td></tr><tr><td>08-09-2020 10:43:10</td><td>YasinShaikh</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	08-09-2020 11:06:29	YasinShaikh	Completed	intercom issues solve and fire alarm issue solved by panel reset access door power supply faulty by supply change work completed		08-09-2020 10:43:22	YasinShaikh	New		-	08-09-2020 10:43:10	YasinShaikh	New		-
Date Time	Technician Name	Status	Remark	Sign																					
08-09-2020 11:06:29	YasinShaikh	Completed	intercom issues solve and fire alarm issue solved by panel reset access door power supply faulty by supply change work completed																						
08-09-2020 10:43:22	YasinShaikh	New		-																					
08-09-2020 10:43:10	YasinShaikh	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>14-07-2023 11:06:26</td><td>Sonu Kumar</td><td>Security cabin fire panel install and 3rd floor MCB light on issue resolved working ok</td></tr><tr><td>03-07-2023 10:44:14</td><td>Kalpesh SubhashGurav</td><td>All Extention Check Done. 110,106,111, Problem Solved Security Gate Ext.100 Problem Solved.</td></tr></tbody></table>					Date Time	Technician Name	Remark	14-07-2023 11:06:26	Sonu Kumar	Security cabin fire panel install and 3rd floor MCB light on issue resolved working ok	03-07-2023 10:44:14	Kalpesh SubhashGurav	All Extention Check Done. 110,106,111, Problem Solved Security Gate Ext.100 Problem Solved.											
Date Time	Technician Name	Remark																							
14-07-2023 11:06:26	Sonu Kumar	Security cabin fire panel install and 3rd floor MCB light on issue resolved working ok																							
03-07-2023 10:44:14	Kalpesh SubhashGurav	All Extention Check Done. 110,106,111, Problem Solved Security Gate Ext.100 Problem Solved.																							