




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4351																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	8451099978																								
Technician Name :	Neeraj Chauhan		Technician Mobile :	8898885764																					
Ticket Type :	Complain	Date & Time :	08-12-2021 10:37:26																						
Vendor Details :																									
Company Name/Client Name :	Dev Research Centre	Customer's Mobile :	8451099978	Name :	Hitesh Doshi																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	06-06-2021 12:00:00		Type :	Comprehensive																					
Product Name :	Time And Attendance																								
Complain :	ip issue																								
Technician Comment :	Port setting in device done Software port chenges Software on static ip done device IP issues solve.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	Port setting in device done Software port chenges Software on static ip done device IP issues solve.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>08-12-2021 05:45:21</td><td>Neeraj Chauhan</td><td>Completed</td><td>Port setting in device done Software port chenges Software on static ip done device IP issues solve.</td><td></td></tr><tr><td>08-12-2021 10:37:37</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr><tr><td>08-12-2021 10:37:26</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	08-12-2021 05:45:21	Neeraj Chauhan	Completed	Port setting in device done Software port chenges Software on static ip done device IP issues solve.		08-12-2021 10:37:37	Neeraj Chauhan	New		-	08-12-2021 10:37:26	Neeraj Chauhan	New		-
Date Time	Technician Name	Status	Remark	Sign																					
08-12-2021 05:45:21	Neeraj Chauhan	Completed	Port setting in device done Software port chenges Software on static ip done device IP issues solve.																						
08-12-2021 10:37:37	Neeraj Chauhan	New		-																					
08-12-2021 10:37:26	Neeraj Chauhan	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>04-02-2022 10:29:01</td><td>Siddhesh Chavan</td><td>PPM work of Aceso , Fire, Epbax done All smoke detector cleaned . and also all door acces checked MCP , hooter fire test done. intercom system working ok all line working ok. 2) 1 st floor biometric machines take to office for checking and finger sensor not working</td></tr><tr><td>08-11-2021 02:53:15</td><td>Neeraj Chauhan</td><td>first floor 3 camera working and 5 camera not working. 5 camera cabling requirement.</td></tr></tbody></table>					Date Time	Technician Name	Remark	04-02-2022 10:29:01	Siddhesh Chavan	PPM work of Aceso , Fire, Epbax done All smoke detector cleaned . and also all door acces checked MCP , hooter fire test done. intercom system working ok all line working ok. 2) 1 st floor biometric machines take to office for checking and finger sensor not working	08-11-2021 02:53:15	Neeraj Chauhan	first floor 3 camera working and 5 camera not working. 5 camera cabling requirement.											
Date Time	Technician Name	Remark																							
04-02-2022 10:29:01	Siddhesh Chavan	PPM work of Aceso , Fire, Epbax done All smoke detector cleaned . and also all door acces checked MCP , hooter fire test done. intercom system working ok all line working ok. 2) 1 st floor biometric machines take to office for checking and finger sensor not working																							
08-11-2021 02:53:15	Neeraj Chauhan	first floor 3 camera working and 5 camera not working. 5 camera cabling requirement.																							