




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE1013</b>																														
<b>Priority :</b>	High																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	9820606496																													
<b>Technician Name :</b>	Zainul Shaikh		<b>Technician Mobile :</b>	8080922971																										
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	29-01-2020 02:24:29																											
<b>Vendor Details :</b>																														
<b>Company Name/Client Name :</b>	Skylone	<b>Customer's Mobile :</b>	9820606496	<b>Name :</b>	Irani Wadi																									
<b>Address :</b>																														
Mumbai , , , , Maharashtra																														
<b>AMC Details :</b>																														
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																											
<b>Product Name :</b>	VDP																													
<b>Complain :</b>	lobby Panel need to Install																													
<b>Technician Comment :</b>	In B wing 15 cable crimping done from Distributor side. all cable check from 1st to 22nd flr.																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	In B wing 15 cable crimping done from Distributor side. all cable check from 1st to 22nd flr.																													
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>29-08-2020 05:16:01</td><td>ZainulShaikh</td><td>Completed</td><td></td><td>-</td></tr><tr><td>29-01-2020 02:26:48</td><td>ZainulShaikh</td><td>Work Pending</td><td>In B wing 15 cable crimping done from Distributor side. all cable check from 1st to 22nd flr.</td><td></td></tr><tr><td>29-01-2020 02:24:37</td><td>ZainulShaikh</td><td>New</td><td></td><td>-</td></tr><tr><td>29-01-2020 02:24:30</td><td>ZainulShaikh</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	29-08-2020 05:16:01	ZainulShaikh	Completed		-	29-01-2020 02:26:48	ZainulShaikh	Work Pending	In B wing 15 cable crimping done from Distributor side. all cable check from 1st to 22nd flr.		29-01-2020 02:24:37	ZainulShaikh	New		-	29-01-2020 02:24:30	ZainulShaikh	New		-
Date Time	Technician Name	Status	Remark	Sign																										
29-08-2020 05:16:01	ZainulShaikh	Completed		-																										
29-01-2020 02:26:48	ZainulShaikh	Work Pending	In B wing 15 cable crimping done from Distributor side. all cable check from 1st to 22nd flr.																											
29-01-2020 02:24:37	ZainulShaikh	New		-																										
29-01-2020 02:24:30	ZainulShaikh	New		-																										
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>24-07-2023 12:03:03</td><td>Atique Salmani</td><td>Lobby camera vewingng issue resolved working ok also one to one working ok.</td></tr><tr><td>05-07-2023 10:16:40</td><td>Ravi Rajbhar</td><td>c wing 1701 door bell issue relsoved only DND Mode enble or diseble seting change</td></tr></tbody></table>					Date Time	Technician Name	Remark	24-07-2023 12:03:03	Atique Salmani	Lobby camera vewingng issue resolved working ok also one to one working ok.	05-07-2023 10:16:40	Ravi Rajbhar	c wing 1701 door bell issue relsoved only DND Mode enble or diseble seting change																
Date Time	Technician Name	Remark																												
24-07-2023 12:03:03	Atique Salmani	Lobby camera vewingng issue resolved working ok also one to one working ok.																												
05-07-2023 10:16:40	Ravi Rajbhar	c wing 1701 door bell issue relsoved only DND Mode enble or diseble seting change																												