Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 Support : | **W** : www.vallabhenterprises.com **E** : vallabhsecure@yahoo.co.in

Service Status Details : VE12417 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9820606496 **No. : Technician Name :** Atique Salmani **Technician Mobile :** 8080922984 **Ticket Type :** Date & Time : 12-08-2024 12:10:24 Complain **Vendor Details :** Customer's Mobile : 9820606496 Irani Wadi Company Skylone Name : Name/Client Name : Address : Mumbai,,,,Maharashtra **AMC Details :** Expiry Date : 01-01-1970 05:30:00 Type : **Product Name :** VDP **Complain**: C-1702 outdoor camera viewing not proper issue **Technician** 1702 lobby view ok there is some sunlight so it's some hazy view but it's sunlight .it's proper . **Comment**: **Complain Operator** Desktop - Apurva Vajaria **Remark** : 1702 lobby view ok there is some sunlight so it's some hazy view but it's sunlight .it's proper . **Status History :** Status **Date Time** Technician Name Remark Sign 16-08-2024 03:16:35 Atique Salmani Completed 1702 lobby view ok there 2 A Ruthod is some sunlight so it's some hazy view but it's sunlight .it's proper . 16-08-2024 03:00:24 Atique Salmani New 13-08-2024 05:46:38 New Atique Salmani **Previous Complain Date Time Technician Name** Remark **History** : 11-11-2024 03:40:41 04-11-2024 04:22:57 Ravi Rajbhar B wing 1504 lobby cmaera viewing issue resolved and ok working done