










Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2206																																			
Priority :	High																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9820606496																																		
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																															
Ticket Type :	Complain	Date & Time :	10-11-2020 10:46:46																																
Vendor Details :																																			
Company Name/Client Name :	Skylone	Customer's Mobile :	9820606496	Name :	Irani Wadi																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	VDP																																		
Complain :	c wing-1304 b wing-1003 , 103																																		
Technician Comment :	1304 c wing NC 01 Faulty cut by eletrician so changed new NC 01 and collect payment also 500 . all working ok.																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	1304 c wing NC 01 Faulty cut by eletrician so changed new NC 01 and collect payment also 500 . all working ok.																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>11-11-2020 03:36:39</td><td>Atique Salmani</td><td>Completed</td><td>1304 c wing NC 01 Faulty cut by eletrician so changed new NC 01 and collect payment also 500 . all working ok.</td><td></td></tr><tr><td>10-11-2020 11:57:11</td><td>Atique Salmani</td><td>Awaiting Spares</td><td>1003 c wing screen Plus door bell camera under repair</td><td></td></tr><tr><td>10-11-2020 11:31:31</td><td>Atique Salmani</td><td>Awaiting Spares</td><td>c wing 1003 sreen and door bell collect for check in office. under repair</td><td></td></tr><tr><td>10-11-2020 10:47:25</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>10-11-2020 10:46:46</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	11-11-2020 03:36:39	Atique Salmani	Completed	1304 c wing NC 01 Faulty cut by eletrician so changed new NC 01 and collect payment also 500 . all working ok.		10-11-2020 11:57:11	Atique Salmani	Awaiting Spares	1003 c wing screen Plus door bell camera under repair		10-11-2020 11:31:31	Atique Salmani	Awaiting Spares	c wing 1003 sreen and door bell collect for check in office. under repair		10-11-2020 10:47:25	Atique Salmani	New		-	10-11-2020 10:46:46	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																															
11-11-2020 03:36:39	Atique Salmani	Completed	1304 c wing NC 01 Faulty cut by eletrician so changed new NC 01 and collect payment also 500 . all working ok.																																
10-11-2020 11:57:11	Atique Salmani	Awaiting Spares	1003 c wing screen Plus door bell camera under repair																																
10-11-2020 11:31:31	Atique Salmani	Awaiting Spares	c wing 1003 sreen and door bell collect for check in office. under repair																																
10-11-2020 10:47:25	Atique Salmani	New		-																															
10-11-2020 10:46:46	Atique Salmani	New		-																															

Previous Complain History :			
	Date Time	Technician Name	Remark
	21-11-2020 10:55:36	Siddhesh Chavan	c wing - 703 lobby video issue solved and all working ok 2) lobby panal is off and stated lobby panal and 1 st to 7 th floor video issue solved
	20-11-2020 11:00:33	Neeraj Chauhan	repair and return vdp install and looby video satting done and b. wing 1901 1902 1001 lobby video issue solved