




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE6818</b>																														
<b>Priority :</b>	Low																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	9820606496																													
<b>Technician Name :</b>	Siddhesh Chavan		<b>Technician Mobile :</b>	8080922985																										
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	11-11-2022 05:13:10																											
<b>Vendor Details :</b>																														
Company Name/Client Name :	Skylone	Customer's Mobile :	9820606496	Name :	Irani Wadi																									
<b>Address :</b>																														
Mumbai , , , , Maharashtra																														
<b>AMC Details :</b>																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
<b>Product Name :</b>	VDP																													
<b>Complain :</b>	C wing 2202 bell not working																													
<b>Technician Comment :</b>	c wing 2202 vdp working ok 22 floor distributor issue because water flow inside need to change distributor and issue resolve																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	c wing 2202 vdp working ok 22 floor distributor issue because water flow inside need to change distributor and issue resolve																													
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>12-11-2022 12:00:42</td><td>Siddhesh Chavan</td><td>Client Side</td><td>c wing 2202 vdp working ok 22 floor distributor issue because water flow inside need to change distributor and issue resolve</td><td></td></tr><tr><td>12-11-2022 10:40:43</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>12-11-2022 10:40:32</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>11-11-2022 05:13:28</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	12-11-2022 12:00:42	Siddhesh Chavan	Client Side	c wing 2202 vdp working ok 22 floor distributor issue because water flow inside need to change distributor and issue resolve		12-11-2022 10:40:43	Siddhesh Chavan	New		-	12-11-2022 10:40:32	Siddhesh Chavan	New		-	11-11-2022 05:13:28	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																										
12-11-2022 12:00:42	Siddhesh Chavan	Client Side	c wing 2202 vdp working ok 22 floor distributor issue because water flow inside need to change distributor and issue resolve																											
12-11-2022 10:40:43	Siddhesh Chavan	New		-																										
12-11-2022 10:40:32	Siddhesh Chavan	New		-																										
11-11-2022 05:13:28	Siddhesh Chavan	New		-																										
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>24-07-2023 12:03:03</td><td>Atique Salmani</td><td>Lobby camera vewinng issue resolved working ok also one to one working ok.</td></tr><tr><td>05-07-2023 10:16:40</td><td>Ravi Rajbhar</td><td>c wing 1701 door bell issue relsoved only DND Mode enble or diseble seting change</td></tr></tbody></table>					Date Time	Technician Name	Remark	24-07-2023 12:03:03	Atique Salmani	Lobby camera vewinng issue resolved working ok also one to one working ok.	05-07-2023 10:16:40	Ravi Rajbhar	c wing 1701 door bell issue relsoved only DND Mode enble or diseble seting change																
Date Time	Technician Name	Remark																												
24-07-2023 12:03:03	Atique Salmani	Lobby camera vewinng issue resolved working ok also one to one working ok.																												
05-07-2023 10:16:40	Ravi Rajbhar	c wing 1701 door bell issue relsoved only DND Mode enble or diseble seting change																												