Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Stat	us Details : VE913									
Priority:	High									
Created By:	Admin - Apurva Vajaria									
Complaint Mob. No. :	9820606496									
Technician Name :	Yasin Shaikh		Technician Mobile :	8689802313						
Ticket Type :	New Installation	Date & Time :	13-01-2020 11:33:42							
Vendor Deta	ils:									
Company Name/Client Name :	Skylone Customer's Mobile :		9820606496	Name :	Irani Wadi					
Address :					•					
Mumbai , ,	, , Maharashtra									
AMC Details	3:									
Expiry Date :	01-01-1970 05:30:00		Type:							
Product Name :	VDP									
Complain:	installation of VDP									
Technician Comment :	18:01:2020 Flat no 1104,604,501,502,504,401,402,404,301,302 with nc01 & crimpisideng donon									
Complain Operator :	Desktop - Apurva Vajaria									
Remark:	18:01:2020 Flat no 1104,604,501,502,504,401,402,404,301,302 with nc01 & crimpisideng donon									

Status History :	Date Time	Techn Nan		Status	Remark	Sign
	24-07-2020 11:38:28	YasinS	haikh	Completed		-
	11-02-2020 04:07:35			Awaiting Spares		-
	18-01-2020 YasinShaik 07:05:41		haikh	In Progress	$18:01:2020 \; \text{Flat no} \; 1104,604,501,502,504,401,402,404,301,302 \; \text{with nc} \\ 01 \; \& \; \text{crimpisideng donon}$	B
	16-01-2020 YasinShaikh 06:54:20		haikh	In Progress	new vdp installation flat no 1401,1403,1404,1301,1302,1303,1304,1201,1202,1203,1204,1101,1102,1103,1003 with nc01 with crimping	
	15-01-2020 05:57:49			In Progress	15:01:2020 06 vdp installation done and nc01 06 nos and crimping flat no 1601,1602,1603,1604,1501,1502 and 2201,2202,2203,2204,2101,2102,2104,2001,2002 nc01 and crimping done	
	14-01-2020 08:28:21	YasinShaikh		In Progress	14: 01: 2020 2004 indoor and outdoor installed all outdoor installed by yasin and all screen installed by me and only 17th floor all crimping done by yogesh ji and 2004 1901.1902.1903.1904 1801.1802.1803.1804.crimping distributer and screen side by me today installed total 13 screen and 12 out door camera becoz one camera bracket screw missing	
	14-01-2020 11:14:20	YasinShaikh		New		-
	14-01-2020 11:14:14	YasinShaikh		In Progress		-
	13-01-2020 05:28:28	YasinS.	haikh	Completed	c wing 2201,2202,2203,2204,2101,2102,2104,2001,2002 and 2003 vdp installation completed. all working properly.	Wir
	13-01-2020 11:33:50	YasinS	haikh	New		-
	13-01-2020 11:33:43	YasinShaikh		New		-
Previous Complain History :	Date Time Tech		Techr	nician Name	Remark	
	24-07-2023 12:03:03 Atio		Atiqu	e Salmani	Lobby camera vewinng issue resolved working ok also one to one working ok.	
	05-07-2023 10:16:40 Ravi Rajbhar		Rajbhar	c wing 1701 door bell issue relsoved only DND Mode enble or diseble seting change		