



# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE7539</b>					
<b>Priority :</b>	Low				
<b>Created By :</b>	Admin - Apurva Vajaria				
<b>Complaint Mob. No. :</b>	9920420594				
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965	
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	04-02-2023 11:10:05		
<b>Vendor Details :</b>					
<b>Company Name/Client Name :</b>	Matunga Kamal Kunj Society	<b>Customer's Mobile :</b>	9920420594	<b>Name :</b>	Jayprakash Kiran Sir Joy
<b>Address :</b>					
Mumbai , , , , Maharashtra					
<b>AMC Details :</b>					
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>		
<b>Product Name :</b>	CCTV				
<b>Complain :</b>	dressing testing of cctv, vdp and intercom				
<b>Technician Comment :</b>	Vdp work completed smae poe injector faulty and all flat vdp check and ok working done All acesss door check all ok working And cctv camera check bandwidth issues resolved and ok working one camera connector faulty main gate and camera remove and hondover to society office and reception camera. Faulty and handover to society office				
<b>Complain Operator :</b>	Desktop - Apurva Vajaria				
<b>Remark :</b>	Vdp work completed smae poe injector faulty and all flat vdp check and ok working done All acesss door check all ok working And cctv camera check bandwidth issues resolved and ok working one camera connector faulty main gate and camera remove and hondover to society office and reception camera. Faulty and handover to society office				

Status History :	<div>Date Time</div>	<div>Technician Name</div>	<div>Status</div>	<div>Remark</div>	<div>Sign</div>
	07-02-2023 07:09:22	Ravi Rajbhar	Completed	Vdp work completed smae poe injector faulty and all flat vdp check and ok working done All acesss door check all ok working And cctv camera check bandwidth issues resolved and ok working one camera connector faulty main gate and camera remove and hondover to society office and reception camera. Faulty and handover to society office	
	06-02-2023 10:04:50	Ravi Rajbhar	New		-
	04-02-2023 04:59:27	Ravi Rajbhar	In Progress	Cctv work progress and vdp work check our side not flat side	
	04-02-2023 11:10:28	Ravi Rajbhar	New		-

Previous Complain History :	<div>Date Time</div>	<div>Technician Name</div>	<div>Remark</div>
	17-02-2023 02:33:11	Sonu Kumar	Time and attendance machine not installed handover to laxman sir Sonu visited on 18.02.2022 with adapter device installed
	11-02-2023 10:20:53	Ravi Rajbhar	Kamal kunj second lift intercom issue resolved and ok working done cable check with lift parson cable one pair breck then second pair used then ok working done all system ok working