Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : VE8312								
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob.	9920420594							
Technician Name :	Siddhesh Chavan		Technician :	Mobile 8080922985				
Ticket Type :	Complain	Date & Time :	10-05-2023	2023 11:43:06				
Vendor Details :								
Company Name/Client Name :	Matunga Kamal Kunj Society	Customer's Mobile :	992042059				Jayprakash Kiran Sir Joy	
Address:								
Mumbai , , , , Maharashtra								
AMC Details :								
Expiry Date :	01-01-1970 05:30:00		Type:					
Product Name:	cCTV-Intercom							
Complain:	1302, society office and some flats intercom issue 20-22 cameras not showing on TV and 2-3 Access card need to add							
Technician Comment :	one new 24 port Poe switch install and 30 camera started and 2 camera take to office for reqpring and one camera installation pending because 2 gate camera cable missing							
Complain Operator :	Desktop - Apurva Vajaria							
Remark:	one new 24 port Poe switch install and 30 camera started and 2 camera take to office for reqpring and one camera installation pending because 2 gate camera cable missing							
Status History :	Date Time	Technician Name	Status		Remark		Sign	
	31-05-2023 07:28:12	Siddhesh Chavan	Work Pending	install an and 2 car reqpring installation	24 port Poe switch d 30 camera starte nera take to office and one camera on pending becaus era cable missing	ed for	M	
	31-05-2023 12:04:29	Siddhesh Chavan	New				-	
	10-05-2023 05:04:06	Siddhesh Chavan	Work Pending	resolved to trrage and 24 pc	e intecom issue and 2 access card and Main lobby di ort Poe switch take checking	ves	James	
	10-05-2023 11:43:16	Siddhesh Chavan	New				-	

Previous Complain History :	Date Time	Technician Name	Remark
	26-07-2023 01:44:45	Ravi Rajbhar	ppm done of cctv systam , access , video door phone and time attandence camplint - 1702 video door phone not working check our side but need to change poe enjector 48 volt and recoding check 26/7/23 to 26/7/23
	19-06-2023 10:59:50	MayurYadav	Vdp install in 802 12 volt power supply use for out door camera Working ok