

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE1029																									
Priority :	High																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9833838795																								
Technician Name :	Mahindra Prajapati		Technician Mobile :	7678020599																					
Ticket Type :	Complain	Date & Time :	31-01-2020 12:27:10																						
Vendor Details :																									
Company Name/Client Name :	Shoppers Stop-ltd Ghatkopar	Customer's Mobile :	9833838795	Name :	Jaywant Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	no display in TV (Complain given by sridhar sir)																								
Technician Comment :	monitor problem solve changing SMPS on client side																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	monitor problem solve changing SMPS on client side																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>31-01-2020 05:57:52</td><td>MahindraPrajapati</td><td>Completed</td><td>monitor problem solve changing SMPS on client side</td><td></td></tr><tr><td>31-01-2020 12:27:19</td><td>MahindraPrajapati</td><td>New</td><td></td><td>-</td></tr><tr><td>31-01-2020 12:27:11</td><td>MahindraPrajapati</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	31-01-2020 05:57:52	MahindraPrajapati	Completed	monitor problem solve changing SMPS on client side		31-01-2020 12:27:19	MahindraPrajapati	New		-	31-01-2020 12:27:11	MahindraPrajapati	New		-
Date Time	Technician Name	Status	Remark	Sign																					
31-01-2020 05:57:52	MahindraPrajapati	Completed	monitor problem solve changing SMPS on client side																						
31-01-2020 12:27:19	MahindraPrajapati	New		-																					
31-01-2020 12:27:11	MahindraPrajapati	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>06-06-2022 11:28:15</td><td>YogeshDesai</td><td>one new power supply installed at check point of staff entry near finger device device and reader working ok</td></tr><tr><td>09-05-2022 07:59:48</td><td>Shiva Meena</td><td>5 dvr port isu balekn whait all camera ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	06-06-2022 11:28:15	YogeshDesai	one new power supply installed at check point of staff entry near finger device device and reader working ok	09-05-2022 07:59:48	Shiva Meena	5 dvr port isu balekn whait all camera ok											
Date Time	Technician Name	Remark																							
06-06-2022 11:28:15	YogeshDesai	one new power supply installed at check point of staff entry near finger device device and reader working ok																							
09-05-2022 07:59:48	Shiva Meena	5 dvr port isu balekn whait all camera ok																							