

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14824																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9819662812																			
Technician Name :	Neeraj Chauhan		Technician Mobile :	8898885764																
Ticket Type :	Complain	Date & Time :	27-05-2025 11:07:57																	
Vendor Details :																				
Company Name/Client Name :	Bellavista Building	Customer's Mobile :	9819662812	Name :	Jivan Patil															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	31-08-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	cCTV-Intercom																			
Complain :	1)Flat No-903 intercom issue 2)Mouse configuration 3)1 camera need to shift - 750/- charges																			
Technician Comment :	903 flat intercom not working because ELv shaft to flat DB intercom cable faulty.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	903 flat intercom not working because ELv shaft to flat DB intercom cable faulty.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>27-05-2025 01:27:52</td><td>Neeraj Chauhan</td><td>Completed</td><td>903 flat intercom not working because ELv shaft to flat DB intercom cable faulty.</td><td></td></tr><tr><td>27-05-2025 11:08:13</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	27-05-2025 01:27:52	Neeraj Chauhan	Completed	903 flat intercom not working because ELv shaft to flat DB intercom cable faulty.		27-05-2025 11:08:13	Neeraj Chauhan	New		-
Date Time	Technician Name	Status	Remark	Sign																
27-05-2025 01:27:52	Neeraj Chauhan	Completed	903 flat intercom not working because ELv shaft to flat DB intercom cable faulty.																	
27-05-2025 11:08:13	Neeraj Chauhan	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>16-06-2025 11:35:49</td><td>Rahul Mhapralkar</td><td>1)Flat No-1904 Intercom not working - Done(Keypad issue) 2)Flat No-903 (cable Ok but not able to call Voltage sowing low as per rahul) & 904 intercom cabling done duct to flat (Cabling not done proper as per rahul)</td></tr><tr><td>11-06-2025 01:35:08</td><td>Rahul Mhapralkar</td><td>1102 complaint resolved, 904 cable not found,903 cable not found.</td></tr></tbody></table>					Date Time	Technician Name	Remark	16-06-2025 11:35:49	Rahul Mhapralkar	1)Flat No-1904 Intercom not working - Done(Keypad issue) 2)Flat No-903 (cable Ok but not able to call Voltage sowing low as per rahul) & 904 intercom cabling done duct to flat (Cabling not done proper as per rahul)	11-06-2025 01:35:08	Rahul Mhapralkar	1102 complaint resolved, 904 cable not found,903 cable not found.						
Date Time	Technician Name	Remark																		
16-06-2025 11:35:49	Rahul Mhapralkar	1)Flat No-1904 Intercom not working - Done(Keypad issue) 2)Flat No-903 (cable Ok but not able to call Voltage sowing low as per rahul) & 904 intercom cabling done duct to flat (Cabling not done proper as per rahul)																		
11-06-2025 01:35:08	Rahul Mhapralkar	1102 complaint resolved, 904 cable not found,903 cable not found.																		