




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3353																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9819662812																								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																					
Ticket Type :	Complain	Date & Time :	02-07-2021 12:56:18																						
Vendor Details :																									
Company Name/Client Name :	Bellavista Building	Customer's Mobile :	9819662812	Name :	Jivan Patil																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	31-08-2021 12:00:00		Type :	Non-Comprehensive																					
Product Name :	Intercom																								
Complain :	system re programming																								
Technician Comment :	intercom system all flat reprogramming done and ok working 902 cable check flat to juction line ok no instrument with cheque callot																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	intercom system all flat reprogramming done and ok working 902 cable check flat to juction line ok no instrument with cheque callot																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>02-07-2021 04:52:58</td><td>Ravi Rajbhar</td><td>Completed</td><td>intercom system all flat reprogramming done and ok working 902 cable check flat to juction line ok no instrument with cheque callot</td><td></td></tr><tr><td>02-07-2021 12:56:37</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>02-07-2021 12:56:18</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	02-07-2021 04:52:58	Ravi Rajbhar	Completed	intercom system all flat reprogramming done and ok working 902 cable check flat to juction line ok no instrument with cheque callot		02-07-2021 12:56:37	Ravi Rajbhar	New		-	02-07-2021 12:56:18	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
02-07-2021 04:52:58	Ravi Rajbhar	Completed	intercom system all flat reprogramming done and ok working 902 cable check flat to juction line ok no instrument with cheque callot																						
02-07-2021 12:56:37	Ravi Rajbhar	New		-																					
02-07-2021 12:56:18	Ravi Rajbhar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>08-08-2023 11:34:18</td><td>DilshadKhan</td><td>In screen cameras not changing issu in 2+2 4+1 cabal 2 mtr and 2 rc pin work pending</td></tr><tr><td>01-08-2023 10:50:00</td><td>Siddhesh Chavan</td><td>2 camera no video issue resoved back side camera DC change and camera working ok and security cabin camera video on off issue resoved and 7th floor reception intrcom issue resolved cantion side recontion</td></tr></tbody></table>					Date Time	Technician Name	Remark	08-08-2023 11:34:18	DilshadKhan	In screen cameras not changing issu in 2+2 4+1 cabal 2 mtr and 2 rc pin work pending	01-08-2023 10:50:00	Siddhesh Chavan	2 camera no video issue resoved back side camera DC change and camera working ok and security cabin camera video on off issue resoved and 7th floor reception intrcom issue resolved cantion side recontion											
Date Time	Technician Name	Remark																							
08-08-2023 11:34:18	DilshadKhan	In screen cameras not changing issu in 2+2 4+1 cabal 2 mtr and 2 rc pin work pending																							
01-08-2023 10:50:00	Siddhesh Chavan	2 camera no video issue resoved back side camera DC change and camera working ok and security cabin camera video on off issue resoved and 7th floor reception intrcom issue resolved cantion side recontion																							