Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status D	etails : VE3568						
Priority :	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9819662812						
Technician Name :	Ravi Rajbhar		Technician Mobile : 808092		8080922965		
Ticket Type :	Complain	Date & Time :	06-08-2021 11:50:54				
Vendor Details :							
Company Name/Client Name :	Bellavista Building	Customer's Mobile :	9819662812		Name :	Jivan Patil	
Address:							
Mumbai , , , , M	aharashtra						
AMC Details:							
Expiry Date :	31-08-2021 12:00:00		Type:		Non-Comprehensive		
Product Name:	Intercom						
Complain:	Repaired Phonomax system need to install						
Technician Comment :	repair phonomax intercom system return with install and all flat programming done and date and time set check all flat ok working done only 1604/1904 flat lock confirm to hasib bhai						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	repair phonomax intercom system return with install and all flat programming done and date and time set check all flat ok working done only 1604/1904 flat lock confirm to hasib bhai						
Status History :	Date Time	Technician Name	Status	Remark		Sign	
	08-08-2021 03:06:08	Ravi Rajbhar	Completed	repair phonomax intercom system return with install and all flat programming done and date and time set check all flat ok working done only 1604/1904 flat lock confirm to hasib bhai			
	07-08-2021 11:03:30	Ravi Rajbhar	New			-	
	07-08-2021 04:21:43	Ravi Rajbhar	Work Pending		obby line issues call ning lobby reception		
	07-08-2021 03:33:13		New			-	
	06-08-2021 11:51:08	<u> </u>	New			-	
	06-08-2021 11:50:54	Ravi Rajbhar	New			-	

Previous Complain History :	Date Time	Technician Name	Remark		
	08-08-2023 11:34:18	DilshadKhan	In screen cameras not changing issu in 2+2 4+1 cabal 2 mtr and 2 rc pin work pending		
	01-08-2023 10:50:00	Siddhesh Chavan	2 camera no video issue resoved back side camera DC change and camera working ok and security cabin camera video on off issue resoved and 7th floor reception intrcom issue resolved cantion side recontion		