







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3709																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9819662812																																		
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																															
Ticket Type :	Complain	Date & Time :	27-08-2021 11:07:05																																
Vendor Details :																																			
Company Name/Client Name :	Bellavista Building	Customer's Mobile :	9819662812	Name :	Jivan Patil																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	31-08-2021 12:00:00		Type :	Non-Comprehensive																															
Product Name :	Intercom																																		
Complain :	security phone issue																																		
Technician Comment :	main door security intercom issue resolved and ok working done only cable issue RJ 11																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	main door security intercom issue resolved and ok working done only cable issue RJ 11																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>30-08-2021 04:57:15</td><td>Ravi Rajbhar</td><td>Completed</td><td>main door security intercom issue resolved and ok working done only cable issue RJ 11</td><td></td></tr><tr><td>30-08-2021 10:44:15</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>27-08-2021 08:03:22</td><td>Ravi Rajbhar</td><td>Work Pending</td><td>one mine entrance line issue resolved and reprogram and lift porgraming panding</td><td></td></tr><tr><td>27-08-2021 11:07:46</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>27-08-2021 11:07:05</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	30-08-2021 04:57:15	Ravi Rajbhar	Completed	main door security intercom issue resolved and ok working done only cable issue RJ 11		30-08-2021 10:44:15	Ravi Rajbhar	New		-	27-08-2021 08:03:22	Ravi Rajbhar	Work Pending	one mine entrance line issue resolved and reprogram and lift porgraming panding		27-08-2021 11:07:46	Ravi Rajbhar	New		-	27-08-2021 11:07:05	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																															
30-08-2021 04:57:15	Ravi Rajbhar	Completed	main door security intercom issue resolved and ok working done only cable issue RJ 11																																
30-08-2021 10:44:15	Ravi Rajbhar	New		-																															
27-08-2021 08:03:22	Ravi Rajbhar	Work Pending	one mine entrance line issue resolved and reprogram and lift porgraming panding																																
27-08-2021 11:07:46	Ravi Rajbhar	New		-																															
27-08-2021 11:07:05	Ravi Rajbhar	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>08-08-2023 11:34:18</td><td>DilshadKhan</td><td>In screen cameras not changing issu in 2+2 4+1 cabal 2 mtr and 2 rc pin work pending</td></tr><tr><td>01-08-2023 10:50:00</td><td>Siddhesh Chavan</td><td>2 camera no video issue resoved back side camera DC change and camera working ok and security cabin camera video on off issue resoved and 7th floor reception intrcom issue resolved cantion side recontion</td></tr></tbody></table>					Date Time	Technician Name	Remark	08-08-2023 11:34:18	DilshadKhan	In screen cameras not changing issu in 2+2 4+1 cabal 2 mtr and 2 rc pin work pending	01-08-2023 10:50:00	Siddhesh Chavan	2 camera no video issue resoved back side camera DC change and camera working ok and security cabin camera video on off issue resoved and 7th floor reception intrcom issue resolved cantion side recontion																					
Date Time	Technician Name	Remark																																	
08-08-2023 11:34:18	DilshadKhan	In screen cameras not changing issu in 2+2 4+1 cabal 2 mtr and 2 rc pin work pending																																	
01-08-2023 10:50:00	Siddhesh Chavan	2 camera no video issue resoved back side camera DC change and camera working ok and security cabin camera video on off issue resoved and 7th floor reception intrcom issue resolved cantion side recontion																																	