Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status De	tails: VE9100					
Priority:	Low					
Created By:	Admin - Apurva Vajaria					
Complaint Mob. No. :	9819662812					
Technician Name :	Kalpesh Subhash Gurav		Technician Mod	8879684054	8879684054	
Ticket Type :	Complain	Date & Time :	08-08-2023 11:3	8-08-2023 11:34:18		
Vendor Details :						
Company Name/Client Name :	Bellavista Building	Customer's Mobile :	9819662812	Name :	Jivan Patil	
Address:						
Mumbai , , , , Ma	harashtra					
AMC Details:	_					
Expiry Date :	31-08-2021 12:00:00 Type:		Non-Comprehe	Non-Comprehensive		
Product Name:	CCTV					
Complain:	In Screen cameras not changing issue in 2-2 minutes					
Technician Comment :	RC Pin Connect Switch With 5 meter RT4 Cable					
Complain Operator :	Desktop - Apurva Vajaria					
Remark:	RC Pin Connect Switch With 5 meter RT4 Cable					
Status History:	Date Time	Technician Name	Status	Remark	Sign	
	10-08-2023 12:55:33	Kalpesh SubhashGur	av Completed	RC Pin Connect Switch With 5 meter RT4 Cable	Parket	
	10-08-2023 10:42:58	Kalpesh SubhashGur	av New		-	
	08-08-2023 12:10:51	Kalpesh SubhashGur	av Work Pending	In screen cameras not changing issu in 2+2 4+1 cabal 2 mtr and 2 rc pin work pending	Achie	
	08-08-2023 11:34:26	Kalpesh SubhashGur	av New		-	
Previous Complain History :	Date Time	Technician Name	,	Remark		
	10-08-2023 04:54:14	Kalpesh SubhashGur	av Security Lobby Issue Solved	Security Lobby TV Issue Solved and Intercom Display Issue Solved		
	01-08-2023 10:50:00	Siddhesh Chavan	change and car camera video o	2 camera no video issue resoved back side camera DC change and camera working ok and security cabin camera video on off issue resoved and 7th floor reception intrcom issue resolved cantion side recontion		