

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE10834																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9833857590																			
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																
Ticket Type :	Complain	Date & Time :	09-02-2024 05:36:06																	
Vendor Details :																				
Company Name/Client Name :	Kiran Tower CHS	Customer's Mobile :	9833857590	Name :	Kalpesh Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	30-06-2020 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	B-901 Rashmi madam home 1 crimping need to do																			
Technician Comment :	One crimping done and connect In normal network swich and there is no plug point so swich is off .only crimpmed .																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	One crimping done and connect In normal network swich and there is no plug point so swich is off .only crimpmed .																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>09-02-2024 05:44:00</td><td>Atique Salmani</td><td>Completed</td><td>One crimping done and connect In normal network swich and there is no plug point so swich is off .only crimpmed .</td><td>Dinesh</td></tr><tr><td>09-02-2024 05:36:15</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	09-02-2024 05:44:00	Atique Salmani	Completed	One crimping done and connect In normal network swich and there is no plug point so swich is off .only crimpmed .	Dinesh	09-02-2024 05:36:15	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
09-02-2024 05:44:00	Atique Salmani	Completed	One crimping done and connect In normal network swich and there is no plug point so swich is off .only crimpmed .	Dinesh																
09-02-2024 05:36:15	Atique Salmani	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>09-02-2024 10:52:22</td><td>Atique Salmani</td><td>Chek boath dvr logs dvr direct off from plug point .</td></tr><tr><td>03-02-2024 12:32:58</td><td>Shiva Meena</td><td>904/704 intercom line issue solve and shouldering 2 telephone line done</td></tr></tbody></table>					Date Time	Technician Name	Remark	09-02-2024 10:52:22	Atique Salmani	Chek boath dvr logs dvr direct off from plug point .	03-02-2024 12:32:58	Shiva Meena	904/704 intercom line issue solve and shouldering 2 telephone line done						
Date Time	Technician Name	Remark																		
09-02-2024 10:52:22	Atique Salmani	Chek boath dvr logs dvr direct off from plug point .																		
03-02-2024 12:32:58	Shiva Meena	904/704 intercom line issue solve and shouldering 2 telephone line done																		