




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE1160																																			
Priority :	High																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9833857590																																		
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																															
Ticket Type :	Complain	Date & Time :	17-02-2020 12:16:01																																
Vendor Details :																																			
Company Name/Client Name :	Kiran Tower CHS	Customer's Mobile :	9833857590	Name :	Kalpesh Sir																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	30-06-2020 12:00:00		Type :	Non-Comprehensive																															
Product Name :	Intercom																																		
Complain :	3-4 line not working also camera not working																																		
Technician Comment :	1301.1302.1403 bwing not getting dial tone from system card so need to check card																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	1301.1302.1403 b wing not getting dial tone from system card so need to check card work completed by gulam as on 27.02.2020																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>28-02-2020 10:49:45</td><td>Atique Salmani</td><td>Completed</td><td></td><td>-</td></tr><tr><td>20-02-2020 10:04:29</td><td>Atique Salmani</td><td>Work Pending</td><td></td><td>-</td></tr><tr><td>19-02-2020 03:48:40</td><td>Atique Salmani</td><td>Awaiting Spares</td><td>1301.1302.1403 bwing not getting dial tone from system card so need to check card</td><td></td></tr><tr><td>19-02-2020 02:31:06</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>17-02-2020 12:16:02</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	28-02-2020 10:49:45	Atique Salmani	Completed		-	20-02-2020 10:04:29	Atique Salmani	Work Pending		-	19-02-2020 03:48:40	Atique Salmani	Awaiting Spares	1301.1302.1403 bwing not getting dial tone from system card so need to check card		19-02-2020 02:31:06	Atique Salmani	New		-	17-02-2020 12:16:02	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																															
28-02-2020 10:49:45	Atique Salmani	Completed		-																															
20-02-2020 10:04:29	Atique Salmani	Work Pending		-																															
19-02-2020 03:48:40	Atique Salmani	Awaiting Spares	1301.1302.1403 bwing not getting dial tone from system card so need to check card																																
19-02-2020 02:31:06	Atique Salmani	New		-																															
17-02-2020 12:16:02	Atique Salmani	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>02-08-2023 05:11:58</td><td>Kalpesh SubhashGurav</td><td>B Wing Lift no.2 intercom issue solved Intercom line running in Duct flat to Duct cable not found</td></tr><tr><td>26-07-2023 10:03:17</td><td>Kalpesh SubhashGurav</td><td>B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK</td></tr></tbody></table>					Date Time	Technician Name	Remark	02-08-2023 05:11:58	Kalpesh SubhashGurav	B Wing Lift no.2 intercom issue solved Intercom line running in Duct flat to Duct cable not found	26-07-2023 10:03:17	Kalpesh SubhashGurav	B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK																					
Date Time	Technician Name	Remark																																	
02-08-2023 05:11:58	Kalpesh SubhashGurav	B Wing Lift no.2 intercom issue solved Intercom line running in Duct flat to Duct cable not found																																	
26-07-2023 10:03:17	Kalpesh SubhashGurav	B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK																																	