Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 Support : | **W** : www.vallabhenterprises.com **E** : vallabhsecure@yahoo.co.in

Service Status Details : VE1740 **Priority** : High **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9833857590 **No. : Technician Mobile Technician Name** Anil Yadav 8080922983 : Complain Date & Time : 26-08-2020 10:07:37 **Ticket Type :** Vendor Details : Company Kiran Tower Customer's Mobile 9833857590 Name : Kalpesh Sir Name/Client Name CHS Address : Mumbai,,,, Maharashtra **AMC Details :** 30-06-2020 12:00:00 Non-Comprehensive Expiry Date : Type : **Product Name :** CCTV **Complain**: wing dvr display has over lay msg And also get the mic connection at desk checked this issue solve. Technician **Comment** : Complain Desktop - Apurva Vajaria **Operator** : **Remark** : this issue solve. **Status History : Technician Name Date Time** Status Remark Sign 09-09-2020 05:10:40 AnilYadav Completed this issue solve. Δ 28-08-2020 07:30:10 Work Pending AnilYadav new mic install working fine. old mic is faulty. Angle CCTV work pending because raining. 28-08-2020 11:42:31 AnilYadav New 27-08-2020 02:36:19 AnilYadav New 27-08-2020 02:31:56 AnilYadav New 27-08-2020 02:01:35 AnilYadav New 26-08-2020 10:07:37 AnilYadav New

| Previous Complain History : | Date Time | Technician Name | Remark |
|-----------------------------------|---------------------|----------------------|---|
| | 02-08-2023 05:11:58 | Kalpesh SubhashGurav | B Wing Lift no.2 intercom issue solved Intercom line running in Duct flat to Duct cable not found |
| | 26-07-2023 10:03:17 | Kalpesh SubhashGurav | B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK |