

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2598																																								
Priority :	Low																																							
Created By :	Admin - Apurva Vajaria																																							
Complaint Mob. No. :	9833857590																																							
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																																				
Ticket Type :	Complain	Date & Time :	21-01-2021 10:08:11																																					
Vendor Details :																																								
Company Name/Client Name :	Kiran Tower CHS	Customer's Mobile :	9833857590	Name :	Kalpesh Sir																																			
Address :																																								
Mumbai , , , , Maharashtra																																								
AMC Details :																																								
Expiry Date :	30-06-2020 12:00:00		Type :	Non-Comprehensive																																				
Product Name :	Intercom																																							
Complain :	b1102 phone to install																																							
Technician Comment :	b wing 1102 cable check and ok working done only instrument issue need chenge new phone on Monday																																							
Complain Operator :	Desktop - Apurva Vajaria																																							
Remark :	b wing 1102 cable check and ok working done only instrument issue need chenge new phone on Monday																																							
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>23-01-2021 06:33:02</td><td>Ravi Rajbhar</td><td>Completed</td><td>b wing 1102 cable check and ok working done only instrument issue need chenge new phone on Monday</td><td></td></tr><tr><td>23-01-2021 12:59:40</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>22-01-2021 10:21:12</td><td>Ravi Rajbhar</td><td>Work Pending</td><td></td><td>-</td></tr><tr><td>21-01-2021 05:53:47</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>21-01-2021 11:05:01</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>21-01-2021 10:08:11</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	23-01-2021 06:33:02	Ravi Rajbhar	Completed	b wing 1102 cable check and ok working done only instrument issue need chenge new phone on Monday		23-01-2021 12:59:40	Ravi Rajbhar	New		-	22-01-2021 10:21:12	Ravi Rajbhar	Work Pending		-	21-01-2021 05:53:47	Ravi Rajbhar	New		-	21-01-2021 11:05:01	Ravi Rajbhar	New		-	21-01-2021 10:08:11	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																																				
23-01-2021 06:33:02	Ravi Rajbhar	Completed	b wing 1102 cable check and ok working done only instrument issue need chenge new phone on Monday																																					
23-01-2021 12:59:40	Ravi Rajbhar	New		-																																				
22-01-2021 10:21:12	Ravi Rajbhar	Work Pending		-																																				
21-01-2021 05:53:47	Ravi Rajbhar	New		-																																				
21-01-2021 11:05:01	Ravi Rajbhar	New		-																																				
21-01-2021 10:08:11	Ravi Rajbhar	New		-																																				
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>02-08-2023 05:11:58</td><td>Kalpesh SubhashGurav</td><td>B Wing Lift no.2 intercom issue solved Intercom line running in Duct flat to Duct cable not found</td></tr><tr><td>26-07-2023 10:03:17</td><td>Kalpesh SubhashGurav</td><td>B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK</td></tr></tbody></table>					Date Time	Technician Name	Remark	02-08-2023 05:11:58	Kalpesh SubhashGurav	B Wing Lift no.2 intercom issue solved Intercom line running in Duct flat to Duct cable not found	26-07-2023 10:03:17	Kalpesh SubhashGurav	B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK																										
Date Time	Technician Name	Remark																																						
02-08-2023 05:11:58	Kalpesh SubhashGurav	B Wing Lift no.2 intercom issue solved Intercom line running in Duct flat to Duct cable not found																																						
26-07-2023 10:03:17	Kalpesh SubhashGurav	B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK																																						