




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE3176</b>																														
<b>Priority :</b>	Low																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	9833857590																													
<b>Technician Name :</b>	Mayur Yadav		<b>Technician Mobile :</b>	8411951301																										
<b>Ticket Type :</b>	New Installation	<b>Date &amp; Time :</b>	03-06-2021 10:44:18																											
<b>Vendor Details :</b>																														
<b>Company Name/Client Name :</b>	Kiran Tower CHS	<b>Customer's Mobile :</b>	9833857590	<b>Name :</b>	Kalpesh Sir																									
<b>Address :</b>																														
Mumbai , , , , Maharashtra																														
<b>AMC Details :</b>																														
<b>Expiry Date :</b>	30-06-2020 12:00:00		<b>Type :</b>	Non-Comprehensive																										
<b>Product Name :</b>	CCTV																													
<b>Complain :</b>	2 cameras new cabling of lift																													
<b>Technician Comment :</b>	two camera install two poe switch install replace with old non poe switch																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	two camera install two poe switch install replace with old non poe switch																													
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-06-2021 07:21:45</td><td>MayurYadav</td><td>Completed</td><td>two camera install two poe switch install replace with old non poe switch</td><td></td></tr><tr><td>05-06-2021 10:35:10</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>03-06-2021 10:44:29</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>03-06-2021 10:44:18</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-06-2021 07:21:45	MayurYadav	Completed	two camera install two poe switch install replace with old non poe switch		05-06-2021 10:35:10	MayurYadav	New		-	03-06-2021 10:44:29	MayurYadav	New		-	03-06-2021 10:44:18	MayurYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																										
05-06-2021 07:21:45	MayurYadav	Completed	two camera install two poe switch install replace with old non poe switch																											
05-06-2021 10:35:10	MayurYadav	New		-																										
03-06-2021 10:44:29	MayurYadav	New		-																										
03-06-2021 10:44:18	MayurYadav	New		-																										
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>02-08-2023 05:11:58</td><td>Kalpesh SubhashGurav</td><td>B Wing Lift no.2 intercom issue solved Intercom line running in Duct flat to Duct cable not found</td></tr><tr><td>26-07-2023 10:03:17</td><td>Kalpesh SubhashGurav</td><td>B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK</td></tr></tbody></table>					Date Time	Technician Name	Remark	02-08-2023 05:11:58	Kalpesh SubhashGurav	B Wing Lift no.2 intercom issue solved Intercom line running in Duct flat to Duct cable not found	26-07-2023 10:03:17	Kalpesh SubhashGurav	B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK																
Date Time	Technician Name	Remark																												
02-08-2023 05:11:58	Kalpesh SubhashGurav	B Wing Lift no.2 intercom issue solved Intercom line running in Duct flat to Duct cable not found																												
26-07-2023 10:03:17	Kalpesh SubhashGurav	B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK																												