Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

| Service Status Deta | ils : VE3206 | | | | | | | |
|-------------------------------|--|---|---------------------|---------|---|-------------------|------|--|
| Priority: | Low | | | | | | | |
| Created By: | Admin - Apurva Vajaria | | | | | | | |
| Complaint Mob. | 9833857590 | | | | | | | |
| Technician Name | Siddhesh Chavan | | Technician Mobile : | | 8080922985 | | | |
| Ticket Type : | Complain | Date & Time : | 07-06-2021 01:30:00 | | | | | |
| Vendor Details : | | | | | | <u>.</u> | | |
| Company Name/Client Name : | Kiran Tower CHS | Customer's Mobile : | 9833857590 | | Name: | Kalpesh Sir | | |
| Address: | | | | | | | | |
| Mumbai , , , , Maha | rashtra | | | | | | | |
| AMC Details : | | | | | | - | | |
| Expiry Date : | 30-06-2020 12:00 | 0:00 | Type: | | | Non-Comprehensive | | |
| Product Name: | CCTV | | | | | | | |
| Complain: | IP cameras issue | | | | | | | |
| Technician Comment : | ip camera issue resolved and all camera working ok | | | | | | | |
| Complain Operator : | Desktop - Apurva Vajaria | | | | | | | |
| Remark: | ip camera issue resolved and all camera working ok | | | | | | | |
| Status History : | Date Time | Technician Name | Status | | | Remark | Sign | |
| | 07-06-2021 03:11:1 | 07-06-2021 03:11:12 Siddhesh Chavan Completed | | mpleted | ip camera issue resolved and all camera working ok | | | |
| | 07-06-2021 01:30:3 | 37 Siddhesh Chavan | New | | | | - | |
| | 07-06-2021 01:30:0 | OO Siddhesh Chavan | New | | | | - | |
| Previous Complain History | Date Time | Technician Na | | | Remark | | | |
| | 02-08-2023 05:11:5 | Kalpesh SubhashC | alpesh SubhashGurav | | B Wing Lift no.2 intercom issue solved Intercom line running in Duct flat to Duct cable not found | | | |
| | 26-07-2023 10:03:1 | Kalpesh SubhashC | | | B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK | | | |