




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3227																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9833857590																													
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																										
Ticket Type :	New Installation	Date & Time :	12-06-2021 10:49:56																											
Vendor Details :																														
Company Name/Client Name :	Kiran Tower CHS	Customer's Mobile :	9833857590	Name :	Kalpesh Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	30-06-2020 12:00:00		Type :	Non-Comprehensive																										
Product Name :	Access																													
Complain :	installation of access																													
Technician Comment :	installed door access strike lock and working ok. also told to Kalpesh sir how to add user. and share also manual to klpesh sir																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	installed door access strike lock and working ok. also told to Kalpesh sir how to add user. and share also manual to klpesh sir																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>16-06-2021 02:08:20</td><td>Atique Salmani</td><td>Completed</td><td>installed door access strike lock and working ok. also told to Kalpesh sir how to add user. and share also manual to klpesh sir</td><td></td></tr><tr><td>16-06-2021 10:07:18</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>12-06-2021 10:50:31</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>12-06-2021 10:49:56</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	16-06-2021 02:08:20	Atique Salmani	Completed	installed door access strike lock and working ok. also told to Kalpesh sir how to add user. and share also manual to klpesh sir		16-06-2021 10:07:18	Atique Salmani	New		-	12-06-2021 10:50:31	Atique Salmani	New		-	12-06-2021 10:49:56	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																										
16-06-2021 02:08:20	Atique Salmani	Completed	installed door access strike lock and working ok. also told to Kalpesh sir how to add user. and share also manual to klpesh sir																											
16-06-2021 10:07:18	Atique Salmani	New		-																										
12-06-2021 10:50:31	Atique Salmani	New		-																										
12-06-2021 10:49:56	Atique Salmani	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>02-08-2023 05:11:58</td><td>Kalpesh SubhashGurav</td><td>B Wing Lift no.2 intercom issue solved Intercom line running in Duct flat to Duct cable not found</td></tr><tr><td>26-07-2023 10:03:17</td><td>Kalpesh SubhashGurav</td><td>B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK</td></tr></tbody></table>					Date Time	Technician Name	Remark	02-08-2023 05:11:58	Kalpesh SubhashGurav	B Wing Lift no.2 intercom issue solved Intercom line running in Duct flat to Duct cable not found	26-07-2023 10:03:17	Kalpesh SubhashGurav	B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK																
Date Time	Technician Name	Remark																												
02-08-2023 05:11:58	Kalpesh SubhashGurav	B Wing Lift no.2 intercom issue solved Intercom line running in Duct flat to Duct cable not found																												
26-07-2023 10:03:17	Kalpesh SubhashGurav	B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK																												