Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 Support : | **W** : www.vallabhenterprises.com **E** : vallabhsecure@yahoo.co.in

Service Status Details : VE3231 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9833857590 **No. : Technician** Ravi Rajbhar **Technician Mobile** 8080922965 Name : Complain 12-06-2021 03:22:50 **Ticket Type :** Date & Time : **Vendor Details :** Customer's Mobile 9833857590 Company Kiran Tower Name : Kalpesh Sir Name/Client CHS Name : **Address** : Mumbai,,,, Maharashtra **AMC Details :** 30-06-2020 12:00:00 Expiry Date : Type : Non-Comprehensive **Product Name :** Intercom **Complain**: 2-3 flats intercom issue b wing 1303 also ok working b wing 1302 line issue resolved a wing line resolved but instrument Technician keypaid issue and instrument remove and return office with check and duct side cable punching **Comment** : 1302 Complain Desktop - Apurva Vajaria **Operator** : b wing 1303 also ok working b wing 1302 line issue resolved a wing line resolved but instrument **Remark** : keypaid issue and instrument remove and return office with check and duct side cable punching 1302 **Status History : Technician Name Date Time** Status Remark Sign 12-06-2021 05:19:17 Ravi Rajbhar Completed b wing 1303 also ok working b wing 1302 line issue resolved Sanak a wing line resolved but instrument keypaid issue and instrument remove and return office with check and duct side cable punching 1302 12-06-2021 03:23:12 New Ravi Rajbhar 12-06-2021 03:23:10 Ravi Rajbhar New 12-06-2021 03:22:51 Ravi Rajbhar New **Previous** Date Time **Technician Name** Remark Complain 02-08-2023 05:11:58 Kalpesh SubhashGurav B Wing Lift no.2 intercom issue solved Intercom line **History** : running in Duct flat to Duct cable not found 26-07-2023 10:03:17 Kalpesh SubhashGurav B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK