## Vallabh Enterprises

**Regd. Office** : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE3293 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9833857590 **No. :** Technician Siddhesh Chavan **Technician Mobile** 8080922985 Name : Complain 24-06-2021 11:09:19 **Ticket Type : Date & Time :** Vendor Details : Kiran Tower Customer's Mobile 9833857590 Kalpesh Sir Company Name : Name/Client Name CHS Address : Mumbai,,,, Maharashtra **AMC Details :** 30-06-2020 12:00:00 Non-Comprehensive Expiry Date : Type : **Product Name :** CCTV **Complain**: 4-5 cameras no link 4 camera no video issue resolved and power cable carban reconstruction and all camera Technician **Comment**: working ok Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 4 camera no video issue resolved and power cable carban reconstruction and all camera working ok **Status History : Date Time Technician Name** Status Remark Sign 24-06-2021 01:53:11 Siddhesh Chavan Completed 4 camera no video issue resolved and power cable carban reconstruction and all camera working ok 24-06-2021 11:09:33 Siddhesh Chavan New Siddhesh Chavan 24-06-2021 11:09:20 New Previous Date Time **Technician Name** Remark Complain **History** : 02-08-2023 05:11:58 Kalpesh SubhashGurav B Wing Lift no.2 intercom issue solved Intercom line running in Duct flat to Duct cable not found B Wing Lift No. 1 Intercom Problem Solved. A And B 26-07-2023 10:03:17 Kalpesh SubhashGurav Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK