Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE333 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9867709139 **No. : Technician Name** Ravi Rajbhar Technician 8080922965 Mobile : Complain 13-09-2019 11:41:06 **Ticket Type :** Date & Time : Vendor Details : **Rahul International** Customer's 9867709139 Company Name : Kalpesh Sir Name/Client Name School CBSE Mobile : Nalasopara West Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** EPABX **Complain**: Line getting disconnected in between of call 3 Ex.no ok working done and two istument issue and one Ex no change canfrom to admin sir Technician **Comment**: work camplet Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 3 Ex.no ok working done and two istument issue and one Ex no change canfrom to admin sir work camplet **Status History : Date Time Technician Name** Status Remark Sign 16-09-2019 06:25:03 Ravi Rajbhar Completed 3 Ex.no ok working done and two istument issue and one Ex no change canfrom to admin sir work camplet 16-09-2019 10:01:20 Ravi Rajbhar New 13-09-2019 12:28:15 Ravi Rajbhar New 13-09-2019 11:41:06 Ravi Rajbhar New Previous **Technician Name Date Time** Remark **Complain History** 19-07-2023 11:00:16 Sonu Kumar Main gate view camera faulty need to change. 06-07-2023 12:47:57 Kalpesh SubhashGurav 1st Floor DVR Online Issue Solved. 3rd Floor Camera Issue Solved. Rahul International (CBSC) New Building 22 Cameras Survey Done. 7 Bullet Camera/ 15 Dome Camera