




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE5403</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9833857590																								
<b>Technician Name :</b>	Chandan Yadav		<b>Technician Mobile :</b>	9833262842																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	07-05-2022 03:47:39																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Kiran Tower	<b>Customer's Mobile :</b>	9833857590	<b>Name :</b>	Kalpesh Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	30-06-2020 12:00:00		<b>Type :</b>	Non-Comprehensive																					
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	3 new camera install and 3 camera need to angle set																								
<b>Technician Comment :</b>	3 new camera install and 5 camera angle sitting. cctv working ok																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	3 new camera install and 5 camera angle sitting. cctv working ok																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>07-05-2022 04:27:55</td><td>ChandanYadav</td><td>Completed</td><td>3 new camera install and 5 camera angle sitting. cctv working ok</td><td></td></tr><tr><td>07-05-2022 03:48:01</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>07-05-2022 03:47:39</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	07-05-2022 04:27:55	ChandanYadav	Completed	3 new camera install and 5 camera angle sitting. cctv working ok		07-05-2022 03:48:01	ChandanYadav	New		-	07-05-2022 03:47:39	ChandanYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																					
07-05-2022 04:27:55	ChandanYadav	Completed	3 new camera install and 5 camera angle sitting. cctv working ok																						
07-05-2022 03:48:01	ChandanYadav	New		-																					
07-05-2022 03:47:39	ChandanYadav	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>05-05-2022 06:08:10</td><td>ChandanYadav</td><td>304 - duck line working and falt to duck to cakble missing</td></tr><tr><td>02-05-2022 10:48:21</td><td>Atique Salmani</td><td>ppm do ne and a wing Terrence camera night issue need to changed and one camera parking also need to changed and b wing dvr duct camera faulty need to changed b wing 403 intercom painding need to recheck client say for next time .also switcher faulty long time need to changed also switcher .</td></tr></tbody></table>					Date Time	Technician Name	Remark	05-05-2022 06:08:10	ChandanYadav	304 - duck line working and falt to duck to cakble missing	02-05-2022 10:48:21	Atique Salmani	ppm do ne and a wing Terrence camera night issue need to changed and one camera parking also need to changed and b wing dvr duct camera faulty need to changed b wing 403 intercom painding need to recheck client say for next time .also switcher faulty long time need to changed also switcher .											
Date Time	Technician Name	Remark																							
05-05-2022 06:08:10	ChandanYadav	304 - duck line working and falt to duck to cakble missing																							
02-05-2022 10:48:21	Atique Salmani	ppm do ne and a wing Terrence camera night issue need to changed and one camera parking also need to changed and b wing dvr duct camera faulty need to changed b wing 403 intercom painding need to recheck client say for next time .also switcher faulty long time need to changed also switcher .																							