Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE5980 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9833857590 **No. : Technician Name** Ravi Rajbhar **Technician Mobile** 8080922965 Complain 18-07-2022 05:29:03 **Ticket Type : Date & Time :** Vendor Details : Kiran Tower Customer's Mobile 9833857590 Company Name : Kalpesh Sir Name/Client Name Address : Mumbai,,,, Maharashtra **AMC Details :** 30-06-2020 12:00:00 Expiry Date : Type : Non-Comprehensive **Product Name :** Intercom **Complain**: b-1403 and a501 Intercom issue b wing 1403 intercom issue resolved a wing 501 duct side cable remove internet parson duct Technician side line ok **Comment** : Complain Desktop - Apurva Vajaria **Operator** : **Remark** : b wing 1403 intercom issue resolved a wing 501 duct side cable remove internet parson duct side line ok **Status History : Date Time Technician Name** Status Remark Sign 18-07-2022 07:37:23 Ravi Rajbhar Completed b wing 1403 intercom issue resolved a wing 501 すがり duct side cable remove internet parson duct side line ok 18-07-2022 05:29:15 Ravi Rajbhar New 18-07-2022 05:29:03 Ravi Rajbhar New Previous **Date Time Technician Name** Remark **Complain History** 21-07-2022 11:11:21 Ravi Rajbhar flat no 1303 intercom issue solved intercom working ok . and main gate camera which was offline is now working camera cable cat six cable blue and green cable is break camera has been given separate power to work camera are working now can be seen online too. 20-07-2022 11:27:55 Ishwar Meena cable root changing B wing work complete