




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7349																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9833857590																								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																					
Ticket Type :	Complain	Date & Time :	12-01-2023 11:35:49																						
Vendor Details :																									
Company Name/Client Name :	Kiran Tower CHS	Customer's Mobile :	9833857590	Name :	Kalpesh Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	30-06-2020 12:00:00		Type :	Non-Comprehensive																					
Product Name :	CCTV																								
Complain :	B wing parking side 1 camera some water issue need to do survey																								
Technician Comment :	Checked the cameras location need to changed cable from dvr end to camera cable approx 50/60 meter rj6 + 2 core .																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	Checked the cameras location need to changed cable from dvr end to camera cable approx 50/60 meter rj6 + 2 core .																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>02-02-2023 11:40:30</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>12-01-2023 12:54:02</td><td>Ravi Rajbhar</td><td>Work Pending</td><td>Checked the cameras location need to changed cable from dvr end to camera cable approx 50/60 meter rj6 + 2 core .</td><td></td></tr><tr><td>12-01-2023 11:37:15</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	02-02-2023 11:40:30	Ravi Rajbhar	New		-	12-01-2023 12:54:02	Ravi Rajbhar	Work Pending	Checked the cameras location need to changed cable from dvr end to camera cable approx 50/60 meter rj6 + 2 core .		12-01-2023 11:37:15	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
02-02-2023 11:40:30	Ravi Rajbhar	New		-																					
12-01-2023 12:54:02	Ravi Rajbhar	Work Pending	Checked the cameras location need to changed cable from dvr end to camera cable approx 50/60 meter rj6 + 2 core .																						
12-01-2023 11:37:15	Ravi Rajbhar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>26-07-2023 10:03:17</td><td>Kalpesh SubhashGurav</td><td>B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK</td></tr><tr><td>24-06-2023 11:22:46</td><td>DilshadKhan</td><td>1 camera ka angle setting issu Resolved and solve 8 floor office ka door lock issu Resolved and solve</td></tr></tbody></table>					Date Time	Technician Name	Remark	26-07-2023 10:03:17	Kalpesh SubhashGurav	B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK	24-06-2023 11:22:46	DilshadKhan	1 camera ka angle setting issu Resolved and solve 8 floor office ka door lock issu Resolved and solve											
Date Time	Technician Name	Remark																							
26-07-2023 10:03:17	Kalpesh SubhashGurav	B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK																							
24-06-2023 11:22:46	DilshadKhan	1 camera ka angle setting issu Resolved and solve 8 floor office ka door lock issu Resolved and solve																							