




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7574																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9833857590																													
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																										
Ticket Type :	Complain	Date & Time :	08-02-2023 11:21:25																											
Vendor Details :																														
Company Name/Client Name :	Kiran Tower	Customer's Mobile :	9833857590	Name :	Kalpesh Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	30-06-2020 12:00:00		Type :	Non-Comprehensive																										
Product Name :	CCTV																													
Complain :	Road side IP camera are offline office door access syst, no cards are working																													
Technician Comment :	Essl x7device installed and 5card add and working ok.																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	Essl x7device installed and 5card add and working ok.																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>15-02-2023 04:01:03</td><td>Atique Salmani</td><td>Completed</td><td>Essl x7device installed and 5card add and working ok.</td><td></td></tr><tr><td>15-02-2023 10:39:00</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>08-02-2023 08:03:54</td><td>Atique Salmani</td><td>Work Pending</td><td>road side camera issue resolved because switch off and reon switch and all camera working ok and 8 th floor one card dives take to office for checking</td><td></td></tr><tr><td>08-02-2023 11:22:11</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	15-02-2023 04:01:03	Atique Salmani	Completed	Essl x7device installed and 5card add and working ok.		15-02-2023 10:39:00	Atique Salmani	New		-	08-02-2023 08:03:54	Atique Salmani	Work Pending	road side camera issue resolved because switch off and reon switch and all camera working ok and 8 th floor one card dives take to office for checking		08-02-2023 11:22:11	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																										
15-02-2023 04:01:03	Atique Salmani	Completed	Essl x7device installed and 5card add and working ok.																											
15-02-2023 10:39:00	Atique Salmani	New		-																										
08-02-2023 08:03:54	Atique Salmani	Work Pending	road side camera issue resolved because switch off and reon switch and all camera working ok and 8 th floor one card dives take to office for checking																											
08-02-2023 11:22:11	Atique Salmani	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>13-02-2023 01:46:42</td><td>YogeshDesai</td><td>Intercom issue of 701 sloved</td></tr><tr><td>21-01-2023 06:21:30</td><td>Siddhesh Chavan</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	13-02-2023 01:46:42	YogeshDesai	Intercom issue of 701 sloved	21-01-2023 06:21:30	Siddhesh Chavan																	
Date Time	Technician Name	Remark																												
13-02-2023 01:46:42	YogeshDesai	Intercom issue of 701 sloved																												
21-01-2023 06:21:30	Siddhesh Chavan																													